




report date: 2024-03-28

General information

| | |
|---------------------|--------------------|
| Make | VOLKSWAGEN |
| Model | POLO MATCH TSI S-A |
| Colour | Grey |
| Year of manufacture | 2021 |
| Top speed | 116 mph |
| 0 - 100 km/h | 11.3 seconds |
| Gearbox | 7 speed Semi Auto |

Engine & fuel consumption

| | |
|-------------------------|------------------------|
| Power | 70 kW / 95 HP / 94 BHP |
| Max. torque | 175 Nm at 2.000 rpm |
| Engine capacity | 999 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 128 g/km |
| CO2 label | D |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-05-28 |
| Pictures | 13 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-24 |
| MOT pass rate | 100 % |
| MOT passed | 1 |
| Failed MOT tests | 0 |
| Total advice items | 8 |
| Total items failed | 0 |

| | |
|--------|------------------|
| MOT #1 | 2024-04-25 12:05 |
|--------|------------------|

| | |
|-----------------|--------------|
| MOT test number | 827892034412 |
|-----------------|--------------|

| | |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

| | |
|------------------|------------|
| Next expiry date | 2025-04-24 |
|------------------|------------|

- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords multiple cut in tread (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords multiple cuts in tread (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
24 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 24 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | G |
| First licence fee (12 months) | £ 210,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  RF21VLW |
| Plate since | 2019-06-29 |
| Current registration |  RF21VLW |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 3 |
| First mileage registration | 2021-06-14 |
| Last registration | 2024-04-25 |
| Complete history | See info |



| | | |
|-----------------|------------|-------|
| Registration #1 | 2021-06-14 | 24 mi |
| Registration #2 | | |
| Registration #3 | | |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 96% |
| Children | 85% |
| Pedestrian | 76% |
| Safety systems | 59% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1751 mm |
| Height | 1461 mm |
| Length | 4053 mm |
| Wheel base | 2551 mm |
| Kerb weight | 1110 kg |
| Max. allowed weight | 1660 kg |

Additional information

| | |
|--------------------|------|
| Fuel tank capacity | 40 l |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DLAC108324 |