





report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Blue
Year of manufacture	2014
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



SW14CNU report date: 2024-03-29

Internet history


Entry 2

Date	2024-02-12
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2021-08-28	
Pictures	19	
Listing price	<u>View report</u>	









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2025-03-19
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	3
Total items failed	9

MOT #10	2024-03-20 09:51
MOT test number	798722838406
Result	✓ Passed
Next expiry date	2025-03-19

MOT #9	2023-09-13 07:52
MOT test number	371964112884
Result	✓ Passed

MOT #8	2022-08-29 12:11
MOT test number	620031898142
Result	✓ Passed
Advice Nearside Rear Service brake binding but not excessively monitor (1.2.1 (f))	

MOT #7	2021-09-16 15:10
MOT test number	275662029234
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT test number

SW14CNU

report date: 2024-03-29

MOT #6 2021-09-13 07:52 774733822100

Result × Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail Offside Rear Brake lever has restricted free movement (1.1.15 (e))

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail Nearside Rear Brake lever has restricted free movement (1.1.15 (e))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #5 2020-10-28 15:27

MOT test number 863693553116

Result ✓ Passed

MOT #4 2020-10-28 11:37

MOT test number 308593250450

Result × Failed

Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #3 2019-05-03 14:36

MOT test number 454828632156

Result ✓ Passed

CarCheck.co.uk page 4/12



All 4 tyres starting to perish at side wall

Advice

SW14CNU report date: 2024-03-29

MOT #2

MOT test number

506288809514

Result

Advice Front brake discs starting to lip

MOT #1	2017-04-19 09:46
MOT test number	846013855521
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	19 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

SW14CNU

report date: 2024-03-29

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-09
Last registration	2024-03-20
Complete history	See info



Registration #1	2014-05-09	27 mi
Registration #2	2017-04-19	13.783 mi
Registration #3	2018-05-03	17.256 mi
Registration #4	2019-05-03	19.521 mi
Registration #5	2020-10-28	25.647 mi
Registration #6	2020-10-28	25.649 mi
Registration #7		11.777 es
Registration #8		0.074
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		0.777 66

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1294 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/3

Number of axles 2

Engine number G4FCEZ336660