





report date: 2024-03-29

General information

Make	NISSAN
Model	PATHFINDER DCI AVENTURA
Colour	Black
Year of manufacture	2008
Top speed	112 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	403 Nm at 2.000 rpm
Engine capacity	2.488 сс
Cylinders	4
Fuel type	Diesel
Consumption city	23.5 mpg
Consumption extra urban	33.2 mpg
Consumption combined	28.8 mpg
CO2 emission	264 g/km
CO2 label	M



CarCheck.co.uk page 1/10



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2021-01-13
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	19
Total items failed	6

MOT #10	2019-07-14 07:15
MOT test number	742478337124
Result	✓ Passed
Next expiry date	2021-01-13

MOT #9	2016-10-12 15:23
MOT test number	675984539103
Result	✓ Passed

MOT #8	2016-10-12 10:57
MOT test number	493577358520
Result	X Failed
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

CarCheck.co.uk page 2/10



Advice

MV58YNS

report date: 2024-03-29

MOT test number

Result

Advice (2.5.C.1a)

Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

Advice (2.5.C.1a)

Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

(2.5.C.1a)

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Oil leak

2014-10-20 17:01

135003794253

✓ Passed

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Oil leak

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Rear Registration plate lamp not working (1.1.C.1d)

MOT #4

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/10



system requires adjustment or repair. (3.7.B.5b)

MV58YNS

report date: 2024-03-29

2013-11-04 11:48 **MOT** #3 **MOT test number** 786468903355 Result × Failed Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b) **Advice Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) Advice Parking brake lever has little reserve travel (3.1.6b) Advice Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking

MOT #2		2012-10-08 10:38
MOT test	number	598352482293
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2011-10-04 13:29
MOT test number	736507671259
Result	✓ Passed

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	NIX.
Flate since	
Current registration	NK SIE
Flate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2008-09-25
Last registration	2019-07-14
Complete history	See info



Registration #1	2008-09-25	18 mi
Registration #2	2011-10-04	13.885 mi
Registration #3	2012-10-08	39.329 mi
Registration #4	2013-11-04	50.630 mi
Registration #5	2013-11-04	50.631 mi
Registration #6	2014-10-20	61.638 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1763 mm
Length	4740 mm
Wheel base	2850 mm
Kerb weight	2204 kg
Max. allowed weight	2880 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 10/10

Number of axles 2

Engine number 965292