





report date: 2024-03-29

## General information

Make	SUZUKI
Model	ALTO SZ2
Colour	Black
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg



CarCheck.co.uk page 1/9



report date: 2024-03-29

### **MOT** history

**MOT #11** 2021-05-05 15:33

MOT test number 499917738544

**Result** ✓ Passed

Next expiry date 2022-05-05

**MOT #10** 2020-05-06 14:32

**MOT test number** 396083115770

Result \( \sqrt{Passed} \)

**Advice** Items removed from driver's view prior to test

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MOT #9 2020-05-06 08:46

**MOT test number** 631149634151

Result X Failed

**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MAJOR Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))

**Advice** Items removed from driver's view prior to test

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

**MAJOR** Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

**MOT #8** 2019-04-30 09:00

**MOT test number** 204407216107

Result \rightarrow Passed

**Advice** Nearside Front Inner evidence of grease around cv boot

Advice Offside Front Tyre worn close to legal limit/worn on edge 155/65/14 (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 155/65/14 (5.2.3 (e))

CarCheck.co.uk page 2/9



report date: 2024-03-29

MOT #7	2018-04-24 10:29

**MOT test number** 453911975420

MOT #6 2017-04-24 15:00

**MOT test number** 610067368470

**Result** ✓ Passed

MOT #5 2016-04-14 12:22

**MOT test number** 371746332417

**Result** 
✓ Passed

MOT #4 2015-05-05 14:20

**MOT test number** 685175925134

**Result** ✓ Passed

MOT #3 2014-02-03 12:52

**MOT test number** 869404134076

**Result** ✓ Passed

MOT #2 2012-04-13 17:27

**MOT test number** 568594702150

**MOT #1** 2012-04-05 14:31

MOT test number 648326092075

Result × Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 3/9



report date: 2024-03-29

## Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 5/9



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		ΚI
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this SUZUKI had different number plates.		
Number of plates		
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 6/9



report date: 2024-03-29

## Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 7/9



GV60NLM report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-01-29
Last registration	2021-05-05
Complete history	See info



Registration #1	2011-01-29	29 mi
Registration #2	2012-04-05	7.511 mi
Registration #3	2012-04-13	7.512 mi
Registration #4	2014-02-03	15.388 mi
Registration #5	2015-05-05	18.590 mi
Registration #6	2016-04-14	23.320 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 8/9



GV60NLM report date: 2024-03-29

Safety ratings

NCAP rating	***
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

# Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	K10BN 1412346

CarCheck.co.uk page 9/9