



HYUNDAI



WGIOPPF


report date: 2024-03-29

General information

Make	HYUNDAI
Model	SANTA FE CRDI PREMIUM
Colour	White
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	436 Nm at 2.500 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	194 g/km
CO2 label	J







Internet history

Entry 1

Date	2021-06-12
Pictures	19
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-11
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	10

MOT #16	2024-04-12 16:13
MOT test number	217125952051
Result	✓ Passed
Next expiry date	2025-04-11
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2024-04-05 13:16
MOT test number	768022667376
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Front passenger door does not latch securely closed (6.2.3 (a))
Fail	Nearside Front Lower Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #14** 2023-03-31 13:31**MOT test number** 131164045230**Result** ✓ Passed**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing edge (5.2.3 (d) (ii))**Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing edge (5.2.3 (d) (ii))**MOT #13** 2023-03-22 10:33**MOT test number** 253715161245**Result** ✗ Failed**Fail** Nearside Rear Suspension arm pin or bush excessively worn tie arm inner bush (5.3.4 (a) (i))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Rear Inner Tyre slightly damaged/cracking or perishing edge (5.2.3 (d) (ii))**Fail** Offside Rear Suspension arm pin or bush excessively worn tie arm inner bush (5.3.4 (a) (i))**Advice** Nearside Rear Inner Tyre slightly damaged/cracking or perishing edge (5.2.3 (d) (ii))**Fail** Offside Front Upper Anti-roll bar attachment bracket/mounting insecure (5.3.3 (a) (i))**MOT #12** 2022-03-16 10:36**MOT test number** 458471880050**Result** ✓ Passed**MOT #11** 2021-03-09 17:45**MOT test number** 610387836578**Result** ✓ Passed

**MOT #10**

2021-03-09 09:42

MOT test number

811905580195

Result**✗ Failed****Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9**

2020-03-23 09:57

MOT test number

869598383610

Result**✓ Passed****MOT #8**

2019-05-08 10:36

MOT test number

316269204689

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**MOT #7**

2019-05-08 08:32

MOT test number

371709023910

Result**✗ Failed****Fail** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension rod pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #6	2018-05-10 12:51
---------------	------------------

MOT test number	830033643309
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2017-05-12 15:45
---------------	------------------

MOT test number	643307891935
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2016-05-11 09:40
---------------	------------------

MOT test number	790771901526
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2015-05-12 16:24
---------------	------------------

MOT test number	817542935125
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2014-05-13 09:32
---------------	------------------

MOT test number	978683434167
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-06-15 11:52
---------------	------------------

MOT test number	257196363480
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
11 April 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	11 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	WG10PPF
Plate since	2024-03-29
Current registration	WG10PPF
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-07-10
Last registration	2024-04-12
Complete history	See info



Registration #1	2010-07-10	25 mi
Registration #2	2013-06-15	39.393 mi
Registration #3	2014-05-13	54.501 mi
Registration #4	2015-05-12	59.156 mi
Registration #5	2016-05-11	65.870 mi
Registration #6	2017-05-12	72.400 mi
Registration #7	2018-05-10	77.989 mi
Registration #8	2019-05-08	85.277 mi
Registration #9	2019-05-08	85.277 mi
Registration #10	2019-05-08	85.277 mi
Registration #11	2019-05-08	85.277 mi
Registration #12	2019-05-08	85.277 mi
Registration #13	2019-05-08	85.277 mi
Registration #14	2019-05-08	85.277 mi
Registration #15	2019-05-08	85.277 mi
Registration #16	2019-05-08	85.277 mi
Registration #17	2019-05-08	85.277 mi
Registration #18	2019-05-08	85.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1890 mm
Height	1760 mm
Length	4660 mm
Wheel base	2700 mm
Kerb weight	1987 kg
Max. allowed weight	2570 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HBAU173687