



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 SPORT
Colour	Blue
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	229 Nm at 4.400 rpm
Engine capacity	2.435 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	31.4 mpg
CO2 emission	215 g/km
CO2 label	K






Internet history

Entry 1

Date	2021-07-09
Pictures	30
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-18
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	46
Total items failed	19

MOT #21 2023-08-22 12:10

MOT test number 420177504772

Result ✓ Passed

Next expiry date 2024-09-18

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20 2023-08-21 10:24

MOT test number 532563844930

Result ✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Headlamp aim too low (4.1.2 (a))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #19**

2022-09-01 11:01

MOT test number

943770989736

Result

✓ Passed

Advice Tyre worn close to legal limit/worn on edge both front tyres close to limit plus cracking in tread area (5.2.3 (e))

Advice Nearside Front headlight slightly opaque

MOT #18

2021-08-24 16:07

MOT test number

775387727184

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2021-08-23 13:46

MOT test number

336624126522

Result

✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #16

2020-09-08 10:36

MOT test number

177505661903

Result

✓ Passed



MOT #15

2019-09-19 15:55

MOT test number

580443824769

Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

**MOT #14**

2019-09-06 12:58

MOT test number

128693953273

Result

✗ Failed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13

2018-07-12 09:34

MOT test number

652074357331

Result

✓ Passed

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #12** 2017-06-20 15:20**MOT test number** 758451399612**Result** ✓ Passed**Advice** Tyre worn close to the legal limit all 4 low on inside edge (4.1.E.1)**MOT #11** 2017-06-20 13:21**MOT test number** 643784238504**Result** ✗ Failed**Fail** Nearside Parking brake operation is causing the vehicle to swerve to the nearside not working (3.7.C.3a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Tyre worn close to the legal limit all 4 low on inside edge (4.1.E.1)**MOT #10** 2016-07-12 14:44**MOT test number** 271210855760**Result** ✓ Passed**MOT #9** 2015-07-14 10:57**MOT test number** 659965695190**Result** ✓ Passed**MOT #8** 2015-07-10 15:48**MOT test number** 857571095104**Result** ✗ Failed**Notice** Nearside front tyre worn on inside edge**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Nearside rear tyre worn on inside wall**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #7** 2014-07-11 17:19**MOT test number** 389632394151**Result** ✓ Passed**MOT #6** 2013-08-01 13:19**MOT test number** 457393313273**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2012-07-24 13:44**MOT test number** 296356502284**Result** ✓ Passed**MOT #4** 2011-07-29 14:30**MOT test number** 829980211200**Result** ✓ Passed**MOT #3** 2010-06-03 15:16**MOT test number** 250074150158**Result** ✓ Passed**Advice** Nearside Front brake disc slightly pitted (3.5.1h)**Advice** Offside Front brake disc slightly pitted (3.5.1h)**MOT #2** 2009-06-08 10:22**MOT test number** 351219159130**Result** ✓ Passed**Advice** Offside Front brake disc slightly pitted (3.5.1h)



MOT #1	2009-06-08 10:22
MOT test number	490489459105
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (1.8)
Pass with rectification	Nearside Front Headlamp aim too low (1.8)
Advice	Offside Front brake disc slightly pitted (3.5.1h)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
18 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-06-09
Last registration	2023-08-22
Complete history	See info



Registration #1	2006-06-09	10 mi
Registration #2	2009-06-08	22.004 mi
Registration #3	2010-06-03	28.198 mi
Registration #4	2011-07-29	33.565 mi
Registration #5	2012-07-24	37.266 mi
Registration #6	2013-08-01	40.744 mi
Registration #7	2014-07-11	44.698 mi
Registration #8	2015-07-10	49.137 mi
Registration #9	2015-07-14	49.137 mi
Registration #10	2016-07-12	54.746 mi
Registration #11	2017-06-20	58.458 mi
Registration #12	2018-06-20	62.277 mi
Registration #13	2019-06-20	66.277 mi
Registration #14	2020-06-20	70.277 mi
Registration #15	2021-06-20	74.277 mi
Registration #16	2022-06-20	78.277 mi
Registration #17	2023-06-20	82.277 mi
Registration #18	2024-06-20	86.277 mi
Registration #19	2025-06-20	90.277 mi
Registration #20	2026-06-20	94.277 mi
Registration #21	2027-06-20	98.277 mi
Registration #22	2028-06-20	102.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1707 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	3940817