



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Black
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





MOT history

MOT expiry date	2021-09-15
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	27
Total items failed	5

MOT #15	2020-08-24 15:48
MOT test number	225408882793
Result	✓ Passed
Next expiry date	2021-09-15
Advice	Vehicle has knocking noise possibly mount or bushes

MOT #14	2020-08-24 12:36
MOT test number	422436218451
Result	✗ Failed
MAJOR	Rear fog lamp not working (4.5.1 (a) (ii))
MAJOR	Rear Shock absorbers has a serious fluid leak both (5.3.2 (b))
MAJOR	Rear Coil spring fractured or broken both (5.3.1 (b) (i))

MOT #13	2019-08-21 13:44
MOT test number	330186770069
Result	✓ Passed
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))

**MOT #12**

2019-08-21 10:24

MOT test number

354934521141

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MAJOR Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm bush (5.3.4 (a) (i))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MAJOR Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Pass with rectification Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #11

2018-09-11 10:00

MOT test number

554494096657

Result**✓ Passed**

Advice Exhaust centre clamp corroded and deteriorated

MOT #10

2018-09-11 09:21

MOT test number

653561759506

Result**✗ Failed**

Advice Exhaust centre clamp corroded and deteriorated

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MAJOR Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #9** 2017-08-22 09:20**MOT test number** 968163385412**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2016-09-15 15:13**MOT test number** 685320506977**Result** ✓ Passed**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #7** 2016-09-14 09:45**MOT test number** 194956306058**Result** ✗ Failed**Fail** Front Tyre tread depth below requirements of 1.6mm both (4.1.E.1)**Advice** Nearside Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)**MOT #6** 2015-09-10 10:09**MOT test number** 602796036681**Result** ✓ Passed**MOT #5** 2014-09-15 10:06**MOT test number** 815298654282**Result** ✓ Passed**MOT #4** 2013-08-28 10:31**MOT test number** 386170243215**Result** ✓ Passed



MOT #3	2012-08-30 10:56
MOT test number	606183042268
Result	✓ Passed

MOT #2	2011-09-08 15:22
MOT test number	396531351284
Result	✓ Passed
<div>Notice Nail in offside rear tyre</div>	

MOT #1	2011-09-07 15:47
MOT test number	985940751280
Result	✗ Failed
<div><div>Notice Nail in offside rear tyre</div><div>Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div><div>Advice Brake pad(s) wearing thin (3.5.1g)</div><div>Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)</div><div>Fail Offside Registration plate lamp not working (1.1.C.1d)</div><div>Advice Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div></div>	



Tax & MOT check

✕
Untaxed

Tax expired:
27 January 2021

✕
MOT

Expired:
15 September 2021

Tax status	Expired at 27 January 2021
Days left	1187 days too late
MOT expiry date	15 September 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-09-15
Last registration	2020-08-24
Complete history	See info



Registration #1	2008-09-15	9 mi
Registration #2	2011-09-07	72.130 mi
Registration #3	2011-09-08	72.130 mi
Registration #4	2012-08-30	81.301 mi
Registration #5	2013-08-28	88.556 mi
Registration #6	2014-09-15	94.686 mi
Registration #7	2015-09-10	100.936 mi
Registration #8	2016-09-14	107.009 mi
Registration #9	2016-09-14	107.009 mi
Registration #10	2016-09-14	107.009 mi
Registration #11	2016-09-14	107.009 mi
Registration #12	2016-09-14	107.009 mi
Registration #13	2016-09-14	107.009 mi
Registration #14	2016-09-14	107.009 mi
Registration #15	2016-09-14	107.009 mi
Registration #16	2016-09-14	107.009 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163