





report date: 2024-03-29

### General information

Make	RENAULT
Model	MEGANE SCENIC FIDJI 16V SCENIC
Colour	Silver
Year of manufacture	2003
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	106 BHP
Max. torque	148 Nm at 3.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	190 g/km
CO2 label	J



CarCheck.co.uk page 1/15



report date: 2024-03-29

## Internet history

### Entry 1

Date 2021-09-01

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-29

## MOT history

MOT expiry date	2024-11-15
MOT pass rate	82 %
MOT passed	18
Failed MOT tests	4
Total advice items	32
Total items failed	7

MOT #22	2023-11-13 15:45
MOT test number	849299341872
Result	<b>✓</b> Passed
Next expiry date	2024-11-15
Advice Front Oil leak, but not excessive engine (8.4.1 (a) (i))	

MOT #21	2023-11-13 12:19
MOT test number	565311068236
Result	<b>X</b> Failed
Advice Front Oil leak, but not excessive engine (8.4.1 (a) (i))	
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its stru	ucture (5.2.3 (d) (ii))

MOT #20	2022-11-14 16:31
MOT test number	435193493250
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Power steering pump has slight seepage (2.1.5 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	

CarCheck.co.uk page 3/15



report date: 2024-03-29

 MOT #19
 2021-11-11 11:59

 MOT test number
 791963408726

 Result
 ✓ Passed

 Advice
 Oil leak, but not excessive (8.4.1 (a) (i))

MOT test number

259441840483

Result

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Front Brake disc significantly and obviously worn both (1.1.14 (a) (i))

MOT #17 2020-10-28 15:53 **MOT** test number 546992648331 Result ✓ Passed **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Power steering pump has slight seepage (2.1.5 (a)) Advice Fluid leak, but not excessive pas pipe\pump (8.4.1 (a) (i)) **Advice** Gearbox mounting defective stabalizer

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #16 2020-10-28 12:02

**MOT test number** 270428463275

Result X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Fluid leak, but not excessive pas pipe\pump (8.4.1 (a) (i))

**Advice** Gearbox mounting defective stabalizer

**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))

**Advice** Power steering pump has slight seepage (2.1.5 (a))

**MOT #15** 2019-04-26 09:24

**MOT test number** 375892118897

**Result** ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT #14 2018-04-26 14:28

MOT test number 841713950284

Result 

Passed

**Advice** Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #13 2017-05-12 13:39

**MOT test number** 700242616390

**Result** ✓ Passed

Advice Offside Front Front position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #12 2017-05-12 11:08

MOT test number 464020598424

**Result** X Failed

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Front Tyre worn close to the legal limit bald on edges (4.1.E.1)

Advice Offside Front Front position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

**MOT #11** 2016-05-12 10:02

**MOT test number** 699892947986

**Result** 
✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #10 2015-05-11 13:51

**MOT test number** 199211235148

**Result** ✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #9	2014-05-13 12:30
MOT test number	497323034173
Result	✓ Passed
MOT #8	2013-05-14 11:34
MOT test number	675874933185
Result	✓ Passed
MOT #7	2012-05-08 15:13
MOT test number	648489522190
Result	✓ Passed
MOT #6	2011-05-12 12:17
MOT test number	738332831185
Result	✓ Passed
MOT #5	2010-05-12 11:10
MOT test number	464132430186
Result	✓ Passed
MOT #4	2009-05-09 11:25
MOT test number	613189629173
Result	<b>✓</b> Passed
Notice Nearside front tyre wearing on inner & outer edges	
<b>Notice</b> Offside front tyre wearing on inner & outer edges	

MOT #3	2008-05-13 11:25
MOT test number	542564138107
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/15



report date: 2024-03-29

 MOT #2
 2007-05-11 11:59

 MOT test number
 280781937140

 MOT #1
 2006-05-11 11:33

 MOT test number
 122481936174

 Result
 ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29

### Tax & MOT check





Expires: 15 November 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	15 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owne have? Check it in the premium report and see all owner registrations. Download the full r		_T
THE PARTY OF THE P		
***************************************		
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		
Current registration	NK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info >	

CarCheck.co.uk page 12/15



report date: 2024-03-29

### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-05-15
Last registration	2023-11-13
Complete history	See info



Registration #1	2003-05-15	25 mi
Registration #2	2006-05-11	19.384 mi
Registration #3	2007-05-11	21.924 mi
Registration #4	2008-05-13	25.306 mi
Registration #5	2009-05-09	28.032 mi
Registration #6	2010-05-12	30.791 mi
Registration #7	2011-05-12	39.436 mi
Registration #8	2012-05-08	47.328 mi
Registration #9	2013-05-14	55.395 mi
Registration #10	2014-05-13	66.330 mi
Registration #11	2015-05-11	73.773 mi
Registration #12	2016-05-12	81.526 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		11.777 es
Registration #22		71.777 es
Registration #23		11.777 es
Registration #24		11.777 au

More info >



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1280 kg

## Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number Carcheck.co.uk	D114144 page 15/15