

Ford



General information

Make	FORD
Model	FUSION FUSION +
Colour	Grey
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	179 g/km
CO2 label	I





MOT history

MOT expiry date	2022-10-11
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	26
Total items failed	4

MOT #13		2021-10-12 14:02
MOT test	number	123536982397
Result		✓ Passed
Next expiry date 2022-10-		2022-10-11
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12	20	21-10-12 14:02
MOT test number		382014414605
Result		🗙 Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	
Advice Offside Front Typ	re worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Advice Front Brake disc	worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	

MOT #11		2020-09-29 12:14
MOT test	number	537614816423
Result		✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b)	(i))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	





MOT #10		2019-09-12 13:37
MOT test	number	230145292855
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4	(b) (i))
Advice	Road wheel slightly distorted all wheels (5.2.2 (c) (i))	

MOT #9	2019-09-12 09:48
MOT test number	963902172935
Result	× Failed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))	
Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4	(b) (i))
MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Road wheel slightly distorted all wheels (5.2.2 (c) (i))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3	.4 (b) (i))
MAJOR Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	





MOT #8		2018-09-06 09:25
MOT test	number	282817463766
Result		Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #7	2018-09-06 09:25
MOT test number	704842646706
Result	× Failed
Pass with rectification	Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
Pass with rectification (4.1.2 (a))	Offside Front Headlamp aim so that beam "kick up" is not visible on the screen
Advice Offside Rear Coi	l spring corroded (5.3.1 (b) (i))
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #6	2017-09-11 09:40
MOT test number	944386706009
Result	✓ Passed
MOT #5	2016-09-03 09:26
MOT test number	650511577207
Result	✓ Passed
MOT #4	2015-09-21 10:41

MOT test	number	812093506093
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit on 2mm (4.1.E.1)	





MOT #3	2014-09-20 10:35
MOT test number	335263964445
Result	✓ Passed
MOT #2	2013-09-23 11:31
MOT test number	259676563281
Result	✓ Passed
MOT #1	2012-04-27 12:35
MOT test number	719538812172
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 30 April 2022	X MOT Expired: 11 October 2022
Tax status	Expired at 30 April 2022
Days left	730 days too late
MOT expiry date	11 October 2022
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrient registration	
Current registration Pate since	
Carrent registration Fate since Carrent registration	
Carrent registration Foto since Foto since Foto since	8000-20-20





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-05-26
Last registration	2021-10-12
Complete history	See info



Registration #1	2009-05-26	7 mi
Registration #2	2012-04-27	10.313 mi
Registration #3	2013-09-23	14.428 mi
Registration #4	2014-09-20	23.546 mi
Registration #5	2015-09-21	33.637 mi
Registration #6	2016-09-03	43.724 mi
Registration #7	2017-09-11	53.656 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.117 esi
Registration #12		11.777 mi
Registration #12 Registration #13		01.000 est 01.000 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg
Additional information	
Fuel tank capacity	45
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles	2
Engine number	9P21532