



 **A056GWP**


report date: 2024-03-28

General information

Make	CITROEN
Model	C2 DESIGN
Colour	Yellow
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	94 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg






## Internet history

### Entry 1

Date	2021-05-20
Pictures	24
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

<b>MOT #16</b>	2021-09-15 13:05
<b>MOT test number</b>	249112243275
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-28
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Registration bulb
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge Nearside & Offside (5.2.3 (e))
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases Silencer pipe (6.1.2 (a))
<b>Advice</b>	Front Macpherson strut top bush or bearing has slight wear or free play, Nearside & Offside

<b>MOT #15</b>	2021-09-13 14:35
<b>MOT test number</b>	858891543900
<b>Result</b>	✗ Failed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Offside Registration bulb
<b>Fail</b>	Offside Front Headlamp insecure (4.1.1 (c))
<b>Fail</b>	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
<b>Advice</b>	Front Macpherson strut top bush or bearing has slight wear or free play, Nearside & Offside
<b>Advice</b>	Front Tyre worn close to legal limit/worn on edge Nearside & Offside (5.2.3 (e))
<b>Fail</b>	Front Windscreen wiper does not clear the windscreen effectively Rubber on wiper arm are torn, Nearside & Offside (3.4 (b) (ii))
<b>Advice</b>	Rear Exhaust has a minor leak of exhaust gases Silencer pipe (6.1.2 (a))

<b>MOT #14</b>	2020-09-21 08:50
<b>MOT test number</b>	122412526834
<b>Result</b>	✓ Passed



**MOT #13** 2019-09-20 09:05

**MOT test number** 867856091369

**Result** ✓ Passed

**MOT #12** 2018-08-31 08:33

**MOT test number** 327586803099

**Result** ✓ Passed

**MOT #11** 2017-09-15 09:41

**MOT test number** 520720804631

**Result** ✓ Passed

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #10** 2016-09-19 08:45

**MOT test number** 624813341824

**Result** ✓ Passed

**Advice** 1 of rear exhaust brackets rusted and broken

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Engine oil leaks

**MOT #9** 2015-09-24 08:34

**MOT test number** 221988899688

**Result** ✓ Passed



**MOT #8** 2014-09-23 09:34

**MOT test number** 255586764275

**Result** ✓ Passed

- Notice** Spare wheel and carrier loose
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Rear offside bump stop missing
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2013-09-10 10:33

**MOT test number** 407403753265

**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #6** 2012-09-24 09:51

**MOT test number** 517058762227

**Result** ✓ Passed

- Notice** Rear offside bump stop missing

**MOT #5** 2011-09-23 09:39

**MOT test number** 615086561295

**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Oil leak



**MOT #4** 2011-09-23 09:39

**MOT test number** 237126761272

**Result** ✗ Failed

**Pass with rectification** Nearside Front Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice** Oil leak

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #3** 2010-09-09 15:10

**MOT test number** 651942250240

**Result** ✓ Passed

**MOT #2** 2010-09-09 10:49

**MOT test number** 320062550492

**Result** ✗ Failed

**Notice** Advise both front discs rusty

**Fail** Exhaust system not adequately supported (7.1.1)

**MOT #1** 2009-09-04 12:01

**MOT test number** 370667049291

**Result** ✓ Passed

**Advice** Nearside Front brake disc slightly scored (3.5.1h)

**Advice** Offside Front brake disc slightly scored (3.5.1h)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



**Finance check**

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-09-28
Last registration	2021-09-15
Complete history	<a href="#">See info</a>



Registration #1	2006-09-28	18 mi
Registration #2	2009-09-04	25.915 mi
Registration #3	2010-09-09	33.221 mi
Registration #4	2010-09-09	33.227 mi
Registration #5	2011-09-23	39.660 mi
Registration #6	2012-09-24	45.257 mi
Registration #7	2013-09-10	50.773 mi
Registration #8	2014-09-23	57.029 mi
Registration #9	2015-09-24	63.755 mi
Registration #10		
Registration #11		
Registration #12		
Registration #13		
Registration #14		
Registration #15		
Registration #16		
Registration #17		

[More info >](#)



Safety ratings

NCAP rating ★★★★☆  
Video [see crash video](#)



Dimensions & weight

Width	1659 mm
Height	1461 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	932 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	FP7T4809007