



report date: 2024-03-29

General information

Make	SUZUKI
Model	JIMNY JLX MODE
Colour	Red
Year of manufacture	2004
Top speed	87 mph
0 - 60 mph	16.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	81 BHP
Max. torque	110 Nm at 4.500 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	36.2 mpg
CO2 emission	184 g/km
CO2 label	I





## MOT history

MOT expiry date	2024-02-02
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	21
Total items failed	6

MOT #20	2023-02-03 09:07
MOT test number	427397392424
Result	✓ Passed
Next expiry date	2024-02-02
Advice	Slight play O/S/F swivel housing
Advice	Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))

MOT #19	2023-02-03 09:07
MOT test number	572247222450
Result	✗ Failed
Advice	Slight play O/S/F swivel housing
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Advice	Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))

MOT #18	2022-01-26 14:51
MOT test number	563097932231
Result	✓ Passed

MOT #17	2021-02-02 14:00
MOT test number	596812076644
Result	✓ Passed

**MOT #16** 2019-10-14 10:50**MOT test number** 707716036786**Result** ✓ Passed

**Advice** Offside Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))

**MOT #15** 2018-10-30 14:58**MOT test number** 222308158351**Result** ✓ Passed

**Advice** Nearside Front swivel housing leaking

**MOT #14** 2018-10-29 13:40**MOT test number** 114274693232**Result** ✗ Failed

- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Central Exhaust has a major leak of exhaust gases cat broken (6.1.2 (a))
- Advice** Nearside Front swivel housing leaking
- Fail** Emissions not tested due to exhaust broken (8.2.1.2 (d))

**MOT #13** 2017-09-05 08:35**MOT test number** 977531224732**Result** ✓ Passed

**Advice** Grease slightly weeping from ns front swivel joint

**MOT #12** 2016-09-01 14:23**MOT test number** 872900320016**Result** ✓ Passed**Advice** Front Brake hose has slight corrosion to ferrules both sides (3.6.B.4e)**Advice** Undercarriage, chassis and suspension components rusty**MOT #11** 2015-09-25 08:36**MOT test number** 525904536146**Result** ✓ Passed**Advice** Nearside Front swivel joint has slight play**MOT #10** 2014-11-13 10:28**MOT test number** 817477414353**Result** ✓ Passed**MOT #9** 2014-10-30 15:39**MOT test number** 639773504345**Result** ✗ Failed**Fail** Front brake application uneven (3.7.B.2)**Notice** Slight binding at o/s front brake**Notice** O/s front disc corroded on inner face**MOT #8** 2013-09-24 15:39**MOT test number** 369577863480**Result** ✓ Passed

**MOT #7** 2012-11-13 12:46**MOT test number** 489888512355**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2011-10-26 15:32**MOT test number** 989279591278**Result** ✓ Passed**Notice** Nearside front tyre scrubbed**Notice** Clutch slipping**MOT #5** 2010-10-19 11:16**MOT test number** 234952290202**Result** ✓ Passed**Notice** Nearside front tyre scrubbed**Notice** High biting point on clutch**MOT #4** 2009-11-04 09:51**MOT test number** 941838409310**Result** ✓ Passed**MOT #3** 2008-11-06 14:47**MOT test number** 414521218303**Result** ✓ Passed**MOT #2** 2007-11-06 11:16**MOT test number** 350450517376**Result** ✓ Passed



MOT #12007-10-08 11:18

MOT test number242411387251

Result

✓ Passed

- Advice

Tyre worn close to the legal limit (4.1.E.1)
- Notice

Sill floor chassi brake pipes surface rust advise to wax oil
- Advice

Brake pad(s) wearing thin (3.5.1g)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>YP54FYA</b>
Plate since	2019-03-29
Current registration	<b>YP54FYA</b>
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2004-11-22
Last registration	2023-02-03
Complete history	<a href="#">See info</a>



Registration #1	2004-11-22	13 mi
Registration #2	2007-10-08	15.289 mi
Registration #3	2007-11-06	15.633 mi
Registration #4	2008-11-06	17.959 mi
Registration #5	2009-11-04	21.147 mi
Registration #6	2010-10-19	23.940 mi
Registration #7	2011-10-26	25.296 mi
Registration #8	2012-11-13	26.255 mi
Registration #9	2013-09-24	29.340 mi
Registration #10	2014-10-30	34.816 mi
Registration #11	2014-11-13	34.814 mi
Registration #12	2015-05-20	35.377 mi
Registration #13	2015-05-20	35.377 mi
Registration #14	2015-05-20	35.377 mi
Registration #15	2015-05-20	35.377 mi
Registration #16	2015-05-20	35.377 mi
Registration #17	2015-05-20	35.377 mi
Registration #18	2015-05-20	35.377 mi
Registration #19	2015-05-20	35.377 mi
Registration #20	2015-05-20	35.377 mi
Registration #21	2015-05-20	35.377 mi

More info >



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3645 mm
Wheel base	2250 mm
Kerb weight	1058 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-1465653