





General information

| Make | MAZDA |
|---------------------|----------------|
| Model | MX-5 I |
| Colour | Black |
| Year of manufacture | 2006 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.4 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 124 BHP |
|-------------------------|---------------------|
| Max. torque | 166 Nm at 4.500 rpm |
| Engine capacity | 1.798 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 28.5 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 38.7 mpg |
| CO2 emission | 174 g/km |
| CO2 label | Н |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-06-17 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk



MOT history

| MOT expiry date | 2022-06-14 |
|--------------------|------------|
| MOT pass rate | 93 % |
| MOT passed | 14 |
| Failed MOT tests | 1 |
| Total advice items | 13 |
| Total items failed | 2 |

| MOT #15 | 2021-06-15 11:17 |
|------------------|------------------|
| MOT test number | 661488826618 |
| Result | ✓ Passed |
| Next expiry date | 2022-06-14 |

| MOT #14 | | 2021-01-23 09:03 |
|----------|---|------------------|
| MOT test | number | 227754322066 |
| Result | | ✓ Passed |
| Advice | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |

| MOT #13 | | 2020-02-01 08:58 |
|----------|---|------------------|
| MOT test | number | 945461983315 |
| Result | | ✓ Passed |
| Advice | Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |

| MOT #12 | 2019-02-02 12:40 |
|-----------------|------------------|
| MOT test number | 467141592687 |
| Result | ✓ Passed |





| MOT #11 | 2018-02-20 13:41 |
|-----------------|------------------|
| MOT test number | 730964797822 |
| Result | ✓ Passed |
| | |
| MOT #10 | 2017-02-25 11:37 |
| MOT test number | 297834794276 |
| Result | ✓ Passed |
| | |
| МОТ #9 | 2016-03-24 17:40 |
| MOT test number | 604031740344 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2016-03-21 14:42 |

| MOT test number | 869865819402 |
|--|--------------|
| Result | 🗙 Failed |
| Fail Offside Front front brake binding (3.7.B.1) | |
| Fail Offside Front coil spring broken (2.4.C.1a) | |

| MOT #7 | 2015-06-30 16:26 |
|---|------------------|
| MOT test number | 505221085110 |
| Result | 🗸 Passed |
| Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2) | |

| MOT #6 | 2014-06-11 11:35 |
|-----------------|------------------|
| MOT test number | 387822464190 |
| Result | ✓ Passed |
| | |

| MOT #5 | 2013-06-21 14:26 |
|-----------------|------------------|
| MOT test number | 288842373153 |
| Result | ✓ Passed |





| MOT #4 | 2012-06-11 16:12 |
|---|------------------|
| MOT test number | 345693562115 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2011-06-07 11:39 |
| MOT test number | 106488251168 |
| Result | ✓ Passed |
| Notice Front brake pads wearing thin on inner pads | |
| Notice Front brake discs badly corroded on inner faces | |
| | |
| MOT #2 | 2010-06-14 11:53 |
| MOT test number | 963605260113 |

| Result | | ✓ Passed |
|--------|---|----------|
| Notice | Front inner brake discs rusted both sides | |
| Notice | Nail in offside rear tyre | |
| Advice | Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Nail in nearside front tyre | |

| MOT #1 | | 2009-06-20 09:54 |
|----------|--------------------------------------|------------------|
| MOT test | number | 702141379125 |
| Result | | ✓ Passed |
| Notice | Front pads require closer inspection | |
| Notice | Front discs corroded on inside face | |



YBO6NYN report date: 2024-03-28

Tax & MOT check

| X Untaxed Tax expired: 12 November 2021 | X MOT Expired: 14 June 2022 |
|--|--|
| Tax status | Expired at 12 November 2021 |
| Days left | 898 days too late |
| MOT expiry date | 14 June 2022 |
| Full MOT history | See MOT history |
| Tax calculation | |

| Vehicle class | 48 |
|---|------------|
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------------|
| Date | FEIDO |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLI |
| Damage 2 | E E H - S - A |
| Date | * |
| Category | AMP. |
| Туре | |

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******* | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| *********** | |
| ******* | |
| | More info > |
| Plate changes | |
| See in this check if this MAZDA had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Correct registration | |
| Plate since | |
| | More info > |





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2006-06-28 |
| Last registration | 2021-06-15 |
| Complete history | See info |



| Registration #1 | 2006-06-28 | 13 mi |
|------------------|------------|------------|
| Registration #2 | 2009-06-20 | 20.484 mi |
| Registration #3 | 2010-06-14 | 35.624 mi |
| Registration #4 | 2011-06-07 | 43.238 mi |
| Registration #5 | 2012-06-11 | 50.739 mi |
| Registration #6 | 2013-06-21 | 55.803 mi |
| Registration #7 | 2014-06-11 | 59.618 mi |
| Registration #8 | 2015-06-30 | 62.056 mi |
| Registration #9 | 2016-03-21 | 62.769 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.777 mi |
| Registration #14 | | 11.777 est |
| Registration #15 | | 11.777 mi |
| Registration #16 | | 11.777 est |
| Registration #17 | | 11.777 esi |
| | | |

More info \rightarrow





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1680 mm |
| Height | 1225 mm |
| Length | 3975 mm |
| Wheel base | 2265 mm |
| Max. allowed weight | 1365 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 50 I |
| | 50 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 2 |