



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VIVARO
Colour	White
Year of manufacture	2016
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	43.5 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 2


Date	2021-08-27
Pictures	7
Listing price	<a href="#">View report</a>



source: yesauto.com

Entry 1

Date	2021-08-19
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-20
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	15
Total items failed	0

MOT #9	2023-09-21 11:29
MOT test number	162759413079
Result	✓ Passed
Next expiry date	2024-09-20
Advice	Both coil spring top mounts are noisy when rotated.

MOT #8	2023-09-15 14:15
MOT test number	912378340186
Result	✗ Failed
MAJOR	Front Lower Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction Mobile phone holder and various boxes and items on top of dash. (3.1 (a) (ii))
MAJOR	Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
Advice	Both coil spring top mounts are noisy when rotated.
MAJOR	Windscreen washer not working (3.5 (a))

MOT #7	2022-09-12 08:22
MOT test number	962234985080
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**MOT #6** 2021-09-10 11:18**MOT test number** 437897679806**Result** ✓ Passed**MOT #5** 2021-09-10 10:50**MOT test number** 690413897337**Result** ✗ Failed**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #4** 2020-10-16 11:28**MOT test number** 386195685173**Result** ✓ Passed**MOT #3** 2020-10-14 09:36**MOT test number** 805392460726**Result** ✗ Failed**MAJOR** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**DANGEROUS** Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #2** 2019-10-11 06:59**MOT test number** 983469607383**Result** ✓ Passed



MOT #1	2019-10-08 13:26
MOT test number	604307836339
Result	✗ Failed
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Central Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 September 2024

Tax status		Valid until 1 September
Days left		126
MOT expiry date		20 September 2024
Full MOT history		<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>KU66XYS</b>
Plate since	2019-06-29
Current registration	 <b>KU66XYS</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-10-19
Last registration	2023-09-21
Complete history	<a href="#">See info</a>



Registration #1	2016-10-19	23 mi
Registration #2	2019-10-08	35.732 mi
Registration #3	2019-10-11	37.533 mi
Registration #4	2020-10-14	43.870 mi
Registration #5	2020-10-16	43.870 mi
Registration #6	2020-10-19	43.870 mi
Registration #7	2020-10-22	43.870 mi
Registration #8	2020-10-25	43.870 mi
Registration #9	2020-10-28	43.870 mi
Registration #10	2020-11-01	43.870 mi
Registration #11	2020-11-04	43.870 mi
Registration #12	2020-11-07	43.870 mi

More info >



Safety ratings

NCAP rating	★★★★
Adult	52%
Children	91%
Pedestrian	53%
Safety systems	57%
Overall rating	61%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	4998 mm
Kerb weight	1800 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	R9M MJ - C006772LWX