





General information

Make	AUDI
Model	TT QUATTRO
Colour	Silver
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	250 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	3.189 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.2 mpg
Consumption extra urban	36.2 mpg
Consumption combined	27.4 mpg
CO2 emission	247 g/km
CO2 label	L





Internet history

Entry 1

Date Pictures 2021-05-28

20

Listing price

View report









source: theaa.com



MOT history

MOT expiry date	2024-05-25
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	23
Total items failed	12

MOT #21	2023-05-19 12:00
MOT test number	724783449781
Result	✓ Passed
Next expiry date	2024-05-25

MOT #20	2022-05-20 12:22
MOT test number	916409061947
Result	✓ Passed

MOT #19	2022-05-17 08:17
MOT test number	719150835065
Result	🗙 Failed
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	

MOT #18	2021-05-26 14:31
MOT test number	590387106373
Result	✓ Passed



W99BLK
report date: 2024-03-28

MOT #17	2021-05-25 13:12
MOT test number	916807740563
Result	🗙 Failed
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #16	2020 07 20 15.06
MOT #16 MOT test number	2020-07-30 15:06 292390778362
Result	∠92390778362 ✓ Passed
Result	
MOT #15	2019-07-18 10:48
MOT test number	407139907473
Result	✓ Passed
MOT #14	2018-08-17 12:51
MOT test number	533092179531
Result	✓ Passed
MOT #13	2017-08-22 11:19
MOT test number	199584760764
Result	✓ Passed
MOT #12	2016-08-23 15:15
MOT #12 MOT test number	317283922418
Result	✓ Passed
I COMIL	V Tusseu



W99	BLK
report date:	2024-03-28

MOT #11	2016-08-23 09:08
MOT test number	272064789461
Result	🗙 Failed
Fail Offside Rear rear brake binding (3.7.B.1)	
FailNearside Rear Outer Stop lamp not working (1.2.1b)	
Fail Nearside Rear Outer Rear position lamp(s) not working (1.1.A.3b)	

MOT #10	2015-09-03 13:19
MOT test number	248407254022
Result	✓ Passed

MOT #9		2014-09-29 15:16
MOT test	number	766802974203
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #8

MOT test number

Decult

Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice (2.5.C.1a)	Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt
Notice	Under-trays fitted obscuring some underside components
Notice	Sill covers fitted and brake pipes running behind covers
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

2013-09-12 11:44

566145353222



MOT #7		2013-09-09 11:03
MOT test	number	905852753202
Result		× Failed
Fail N	learside Rear Wheel bolt(s) missing (4.2.A.1e)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	
Notice	Sill covers fitted and brake pipes running behind covers	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Outer Front constant velocity joint gaiter damaged, but preventing the	ingress of dirt
(2.5.C.1a)		
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #6	2012-09-26 12:16
MOT test number	347660472438
Result	✓ Passed
Advice Rear Brake pad(s) wearing thin (3.5.1g)	
MOT #5	2011-09-15 08:40

MOT test number	156978851280
Result	✓ Passed

MOT #4	2011-09-14 16:18
MOT test number	386507951471
Result	🗙 Failed
Fail Nearside Rear position lamp(s) not working (1.1.A.3b)	

MOT #3	2010-09-20 13:04
MOT test number	514893360256
Result	✓ Passed

W99BLK

report date: 2024-03-28



MOT #2			2009-08-29 10:30
MOT test n	number		182431749205
Result			✓ Passed
Advice	Offside Front Bra	ke pad(s) wearing thin (3.5.1g)	
Notice	Nail in O/S/R tyre	e, punctured, too close to side wall to repair.	
Advice	Nearside Front B	rake pad(s) wearing thin (3.5.1g)	
MOT #1			2009-08-29 10:30
MOT test n	number		192611349282
Result			🗙 Failed
Notice Nail in O/S/R tyre, punctured, too close to side wall to repair.			
Pass with	h rectification	Offside Front Windscreen washer provides insufficient was	sher liquid (8.2.3)
Advice Offside Front Brake pad(s) wearing thin (3.5.1g)			
Pass with	h rectification	Nearside Headlamp aim too low (1.8)	
Pass with	h rectification	Nearside Front Windscreen washer provides insufficient w	asher liquid (8.2.3)
Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)			

Pass with rectification Offside Headlamp aim too low (1.8)





Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 September 2024	Expires: 25 May 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et al
Date	*
Category	AMP
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Current registration	
Plate since	



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-09-16
Last registration	2023-05-19
Complete history	See info



Registration #1	2006-09-16	19 mi
Registration #2	2009-08-29	26.451 mi
Registration #3	2010-09-20	35.357 mi
Registration #4	2011-09-14	42.783 mi
Registration #5	2011-09-15	42.783 mi
Registration #6	2012-09-26	49.645 mi
Registration #7	2013-09-09	55.405 mi
Registration #8	2013-09-12	55.438 mi
Registration #9	2014-09-29	64.864 mi
Registration #10	2015-09-03	70.573 mi
Registration #11	2016-08-23	73.881 mi
Registration #12		11.777 est
Registration #13		11.777 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 est
Registration #18		11.777 est
Registration #19		11.777 mi
Registration #20		11.777 est
Registration #21		11.777 mi
Registration #22		11.777 est

More info \rightarrow





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1842 mm
Height	1352 mm
Length	4178 mm
Wheel base	2468 mm
Kerb weight	1410 kg
Max. allowed weight	1810 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles	2
Engine number	BUB 014889