



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT MATCH TDI DSG 105
Colour	Black
Year of manufacture	-
Top speed	115 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg



**MOT history****MOT #20**

2022-03-30 13:39

MOT test number

358356342872

Result

✓ Passed

Next expiry date

2023-03-29

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Road wheel slightly distorted O/S/F O/S/R N/S/R (5.2.2 (c) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Minor** Suspension arm ball joint dust cover severely deteriorated both front lower covers (5.3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2022-03-30 08:40

MOT test number

875434242636

Result

✗ Failed

- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Minor** Suspension arm ball joint dust cover severely deteriorated both front lower covers (5.3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Rear Tyre has ply or cords exposed 215 55 16 (5.2.3 (d) (ii))
- Advice** Road wheel slightly distorted O/S/F O/S/R N/S/R (5.2.2 (c) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Registration plate insecure but not likely to fall off (0.1 (a))

MOT #18

2021-03-24 15:22

MOT test number

204478168112

Result

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17** 2020-03-23 16:28**MOT test number** 659622705091**Result** ✓ Passed**MOT #16** 2020-03-23 12:38**MOT test number** 149871635828**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-03-27 13:11**MOT test number** 947680345356**Result** ✓ Passed**MOT #14** 2019-03-25 13:59**MOT test number** 356445937770**Result** ✗ Failed**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Nail in tyre**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #13** 2018-03-21 11:45**MOT test number** 988863748940**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #12** 2018-03-21 08:54**MOT test number** 270077717640**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside rear tyre worn on inner edge**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #11** 2017-03-30 13:49**MOT test number** 275117053452**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2017-03-30 08:38

MOT test number

644706849758

Result**✗ Failed****Advice**

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail

Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

Fail

Offside Side repeater excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)

Advice

Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #9

2016-03-29 16:48

MOT test number

792844889142

Result**✓ Passed****Advice**

Nearside Front Lower Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice

Child seats fitted to both rear outer seats not allowing inspection of seat belt

Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement console bush (2.4.G.2)

Advice

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement console bush (2.4.G.2)

**MOT #8** 2016-03-29 08:16**MOT test number** 165050630259**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Nearside Front Lower Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement console bush (2.4.G.2)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Child seats fitted to both rear outer seats not allowing inspection of seat belt**Fail** Offside Front Upper Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement console bush (2.4.G.2)**MOT #7** 2015-03-24 11:07**MOT test number** 729003385036**Result** ✓ Passed**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-03-24 11:56**MOT test number** 108623884424**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2013-03-20 09:02**MOT test number** 336559773037**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** All three wiper blades starting to smear**MOT #4** 2013-03-20 09:02**MOT test number** 549749973045**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)**Notice** All three wiper blades starting to smear**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #3** 2012-03-30 16:03**MOT test number** 818700992066**Result** ✓ Passed**MOT #2** 2012-03-29 12:25**MOT test number** 759609382043**Result** ✗ Failed**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2011-03-07 08:44**MOT test number** 688416861080**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 WV08FYN
Plate since	2019-03-29
Current registration	 WV08FYN
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-03-18
Last registration	2022-03-30
Complete history	See info



Registration #1	2008-03-18	16 mi
Registration #2	2011-03-07	60.383 mi
Registration #3	2012-03-29	68.855 mi
Registration #4	2012-03-30	68.855 mi
Registration #5	2013-03-20	77.520 mi
Registration #6	2014-03-24	87.360 mi
Registration #7	2015-03-24	97.567 mi
Registration #8	2016-03-29	107.699 mi
Registration #9	2016-03-29	107.699 mi
Registration #10	2017-03-30	117.283 mi
Registration #11	2018-03-29	127.377 mi
Registration #12	2019-03-29	137.471 mi
Registration #13	2020-03-29	147.565 mi
Registration #14	2021-03-29	157.659 mi
Registration #15	2022-03-29	167.753 mi
Registration #16	2023-03-29	177.847 mi
Registration #17	2024-03-29	187.941 mi
Registration #18	2025-03-29	198.035 mi
Registration #19	2026-03-29	208.129 mi
Registration #20	2027-03-29	218.223 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Max. allowed weight	1920 kg

Additional information

Number of seats	5
Number of axles	2
Engine number	BXE 676824