



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 280 LR P/V
Colour	White
Year of manufacture	2012
Gearbox	6 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	310 Nm at 1.300 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	43.5 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-15
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-23
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	22
Total items failed	11

MOT #14 2024-02-24 11:58

MOT test number 594448328139

Result ✓ Passed

Next expiry date 2025-02-23

**Advice** Brake pipe corroded, covered in grease or other material all sides front to rear (1.1.11 (c))

**Advice** Offside Rear Stop lamp(s) slightly affected by the operation of another lamp (4.3.3 (b))

**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Rear fog lamp slightly affected by the operation of another lamp (4.5.4 (b))

MOT #13 2023-02-21 18:51

MOT test number 873861527926

Result ✓ Passed

**Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

MOT #12 2022-02-09 15:41

MOT test number 603745082467

Result ✓ Passed



MOT #11	2022-02-08 17:13
MOT test number	397763314450
Result	✗ Failed
Fail	Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #10	2021-02-20 11:10
MOT test number	391502856926
Result	✓ Passed
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear pin/bush (5.3.4 (a) (i))
Minor	Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Minor	Front Lower Suspension arm ball joint dust cover severely deteriorated both arms (5.3.4 (b) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear pin/bush (5.3.4 (a) (i))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #9	2020-02-20 12:41
MOT test number	273451050292
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Offside Suspension arm pin or bush worn but not resulting in excessive movement rear bush in arm (5.3.4 (a) (i))

**MOT #8** 2020-02-20 10:53**MOT test number** 994693609632**Result** ✗ Failed**Advice** Offside Suspension arm pin or bush worn but not resulting in excessive movement rear bush in arm (5.3.4 (a) (i))**Fail** Offside Rear Rear fog lamp lens defective such that emitted light is adversely affected (4.5.1 (b) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Nearside Rear Rear fog lamp lens defective which has no effect on emitted light (4.5.1 (b) (i))**MOT #7** 2019-02-21 11:08**MOT test number** 805895271821**Result** ✓ Passed**MOT #6** 2018-02-22 11:41**MOT test number** 234336127780**Result** ✓ Passed**MOT #5** 2018-02-22 11:10**MOT test number** 913210576303**Result** ✗ Failed**Fail** Central Rear Registration plate lamp not working both number plate lights not working (1.1.C.1d)**Fail** Offside Front Front position lamp(s) not working osf side light not working (1.1.A.3b)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick osf brake pads less than 1.5 (3.5.1g)**Fail** Offside Rear Direction indicators incorrect colour osr indicator showing Wight light (1.4.A.2f)



<b>MOT #4</b>	2017-01-31 10:14
---------------	------------------

<b>MOT test number</b>	899668663492
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2016-02-05 13:06
---------------	------------------

<b>MOT test number</b>	896838745510
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2015-05-20 13:26
---------------	------------------

<b>MOT test number</b>	326460445169
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Notice</b>	Nearside lower windscreen cracked.
---------------	------------------------------------

<b>Advice</b>	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
---------------	---

<b>MOT #1</b>	2015-05-20 13:26
---------------	------------------

<b>MOT test number</b>	665570345106
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Notice</b>	Nearside lower windscreen cracked.
---------------	------------------------------------

<b>Advice</b>	Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
---------------	---

<b>Pass with rectification</b>	Nearside Registration plate lamp not working (1.1.C.1d)
--------------------------------	---



Tax & MOT check

✗  
Untaxed

Tax expired:  
1 December 2023

✓  
MOT

Expires:  
23 February 2025

Tax status	Expired at 1 December 2023
Days left	149 days too late
MOT expiry date	23 February 2025
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-31
Last registration	2024-02-24
Complete history	<a href="#">See info</a>



Registration #1	2012-05-31	6 mi
Registration #2	2015-05-20	21.585 mi
Registration #3	2016-02-05	25.721 mi
Registration #4	2017-01-31	40.296 mi
Registration #5	2018-02-22	59.516 mi
Registration #6	2018-02-22	59.516 mi
Registration #7	2019-02-21	77.534 mi
Registration #8	2020-02-20	95.285 mi
Registration #9	2020-05-20	113.036 mi
Registration #10	2020-08-20	130.787 mi
Registration #11	2020-11-20	148.538 mi
Registration #12	2021-02-20	166.289 mi
Registration #13	2021-05-20	184.040 mi
Registration #14	2021-08-20	201.791 mi
Registration #15	2021-11-20	219.542 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BM22795