



General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	124 g/km
CO2 label	D





## Internet history

### Entry 2

Date 2023-12-14

Pictures 6



source: g3remarketing.co.uk

### Entry 1

Date 2021-08-22

Pictures 7

Listing price [View report](#)



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-10
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	2

MOT #9	2024-02-03 11:19
MOT test number	424582193576
Result	✓ Passed
Next expiry date	2025-02-10

MOT #8	2023-02-11 14:16
MOT test number	564264094338
Result	✓ Passed

MOT #7	2021-10-06 15:09
MOT test number	846746729012

Result	✓ Passed
--------	----------

**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Exhaust back box outer casing corroded

MOT #6	2021-02-25 17:03
MOT test number	824154977609

Result	✓ Passed
--------	----------

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2020-02-25 16:32**MOT test number** 527758498366**Result** ✓ Passed**MOT #4** 2020-02-25 16:32**MOT test number** 404626449847**Result** ✗ Failed

**Pass with rectification** Nearside Rear Position lamp with a multiple light source more than 1/2 not functioning (4.2.1 (a) (ii))

**MOT #3** 2019-02-26 16:21**MOT test number** 731272920834**Result** ✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Mirror casing damaged

**MOT #2** 2018-03-06 17:53**MOT test number** 975451708994**Result** ✓ Passed**MOT #1** 2018-03-06 16:56**MOT test number** 989116909707**Result** ✗ Failed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Daytime running light inoperative

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
10 February 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	10 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-01
Last registration	2024-02-03
Complete history	<a href="#">See info</a>



Registration #1	2015-03-01	13 mi
Registration #2	2018-03-06	31.640 mi
Registration #3	2018-03-06	31.642 mi
Registration #4	2019-02-26	41.777 mi
Registration #5	2020-02-25	55.539 mi
Registration #6	2020-02-25	55.539 mi
Registration #7	2020-02-25	55.539 mi
Registration #8	2020-02-25	55.539 mi
Registration #9	2020-02-25	55.539 mi
Registration #10	2020-02-25	55.539 mi
Registration #11	2020-02-25	55.539 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1146933