



General information

Make	VOLKSWAGEN
Model	TIGUAN GTD
Colour	White
Year of manufacture	2010
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	168 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E







Internet history

Entry 1

Date	2021-06-08
Pictures	9
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-05-27
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	24
Total items failed	1

## MOT #12 2023-05-19 09:17

MOT test number 215760225147

Result ✓ Passed

Next expiry date 2024-05-27

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

## MOT #11 2022-05-19 09:28

MOT test number 106032180711

Result ✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #10**

2021-05-05 10:03

**MOT test number**

775191295864

**Result**

✓ Passed

**Advice** Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement (front arm REAR bush detected on shaker plates) (5.3.4 (a) (i))

**MOT #9**

2020-05-07 12:59

**MOT test number**

253277814221

**Result**

✓ Passed

**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (rear arm bush) (5.3.4 (a) (i))

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (cracking perishing) (5.2.3 (e))

**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (rear arm bush ) (5.3.4 (a) (i))

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8**

2020-05-07 08:40

**MOT test number**

766081569910

**Result**

✗ Failed

**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (cracking perishing) (5.2.3 (e))

**Advice** Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (rear arm bush) (5.3.4 (a) (i))

**Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (rear arm bush ) (5.3.4 (a) (i))

**Fail** Nearside Rear Upper Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #7** 2019-05-08 15:55**MOT test number** 378462474092**Result** ✓ Passed

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both front lower arms rear bushes (5.3.4 (a) (i))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened slight corrosion to both front inner faces (1.1.14 (a) (ii))

**MOT #6** 2018-05-13 09:00**MOT test number** 111099840038**Result** ✓ Passed**MOT #5** 2017-05-08 10:49**MOT test number** 117111433510**Result** ✓ Passed**MOT #4** 2016-05-16 10:08**MOT test number** 724783638082**Result** ✓ Passed**MOT #3** 2015-05-13 09:44**MOT test number** 309593235197**Result** ✓ Passed**MOT #2** 2014-05-18 10:02**MOT test number** 458008434149**Result** ✓ Passed**MOT #1** 2013-05-22 10:45**MOT test number** 827402443170**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-05-27
Last registration	2023-05-19
Complete history	<a href="#">See info</a>



Registration #1	2010-05-27	18 mi
Registration #2	2013-05-22	33.887 mi
Registration #3	2014-05-18	37.734 mi
Registration #4	2015-05-13	41.706 mi
Registration #5	2016-05-16	45.478 mi
Registration #6	2017-05-08	48.985 mi
Registration #7	2018-05-13	51.975 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2020-05-20	58.277 mi
Registration #10	2021-05-20	61.277 mi
Registration #11	2022-05-20	64.277 mi
Registration #12	2023-05-19	67.277 mi
Registration #13	2023-05-19	70.277 mi
Registration #14	2023-05-19	73.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

CBB319694