





report date: 2024-03-29

General information

| Make | KIA |
|---------------------|-----------------------|
| Model | SORENTO CRDI KX-2 ISG |
| Colour | Grey |
| Year of manufacture | 2016 |
| Top speed | 124 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 197 BHP |
|-------------------------|---------------------|
| Max. torque | 441 Nm at 1.750 rpm |
| Engine capacity | 2.199 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 39.8 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-06-22

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-06-28 |
|--------------------|------------|
| MOT pass rate | 63 % |
| MOT passed | 5 |
| Failed MOT tests | 3 |
| Total advice items | 17 |
| Total items failed | 11 |

| MOT #8 | | 2023-06-16 08:19 |
|---|--|------------------|
| MOT test | number | 542811613454 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-06-28 |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Advice | Front Registration plate deteriorated but not likely to be misread (0. | 1 (b)) |

CarCheck.co.uk page 3/12



MOT #7 2023-06-13 10:14

MOT test number 126321352410

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Suspension arm pin or bush excessively worn trailing arm bush (5.3.4 (a) (i))

MOT #6 2022-06-29 08:51

MOT test number 960002255629

Result \(\sqrt{Passed} \)

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge wearing on outer edge (5.2.3 (e))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/12



Result

Advice

NA16AOJ report date: 2024-03-29

× Failed

MOT #5 2021-06-26 11:54

MOT test number 916178759526

Result \(\sqrt{Passed} \)

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #4 2021-06-22 15:11

MOT test number 104816456342

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-10-01 09:37

MOT test number 565952563189

MOT #2 2020-10-01 08:32

MOT test number 485509193578

Result × Failed

Fail Central Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #1 2019-03-22 13:02

MOT test number 577147453546

Result

Passed

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 28 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Plate since

Plate since

NA16AOJ

report date: 2024-03-29

EXCESS

More info >

| Owner history | | | |
|---|----------|---|--|
| For how long did the current and previous owner(s) have this KIA? How many owners did this KIA Check it in the premium report and see all owner registrations. Download the full report here . | A have? | | |
| ********* | | | |
| | | | |
| *************************************** | | | |
| ********* | | | |
| | | | |
| *************************************** | | | |
| Мо | ore info | > | |
| Plate changes | | | |
| See in this check if this KIA had different number plates. | | | |
| Number of plates | | | |
| | | | |

CarCheck.co.uk page 9/12



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2016-04-20 |
| Last registration | 2023-06-16 |
| Complete history | See info |



| Registration #1 | 2016-04-20 | 19 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2019-03-22 | 33.507 mi |
| Registration #3 | 2020-10-01 | 46.054 mi |
| Registration #4 | 2020-10-01 | 46.054 mi |
| Registration #5 | 2021-06-22 | 50.388 mi |
| | | |
| Registration #6 | | 11.777 es |
| | | 11.777 ea 11.777 ea |
| Registration #6 | | 11.77 m |
| Registration #6 Registration #7 | | 11.777 es 11.777 es 11.777 es |

More info >

CarCheck.co.uk page 11/12




Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 83% |
| Pedestrian | 67% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1890 mm |
|---------------------|---------|
| Height | 1685 mm |
| Length | 4780 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1932 kg |
| Max. allowed weight | 2590 kg |

Additional information

| Fuel tank capacity | 71 |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 12/1 |

Number of axles 2

Engine number D4HBFH259505