





report date: 2024-03-29

General information

Make	HYUNDAI
Model	VELOSTER GDI SPORT
Colour	White
Year of manufacture	-
Top speed	125 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 4.850 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.9 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-17

Pictures 3

Listing price <u>View report</u>







source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

Advice

Advice

MOT #10	2022-01-21 11:30
MOT test number	780345734683
Result	✓ Passed
Next expiry date	2023-01-20
MOT #9	2021-06-08 08:30
MOT test number	775802201439
Result	✓ Passed
Advice Nearside Front Brake pipe corroded, covered in grease or other	er material (1.1.11 (c))

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8	2020-05-22 12:44
MOT test number	277198397773
Result	✓ Passed
MOT #7	2020-05-20 12:00
MOT test number	437901269443
Result	★ Failed
Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

MOT #6	2019-04-15 09:28
MOT test number	420714296496
Result	✓ Passed
MOT #5	2018-04-12 10:35
MOT test number	494092558534
Result	✓ Passed

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #4 2017-03-30 10:59

MOT test number 891911947023

Result
✓ Passed

MOT #3 2016-03-30 13:12

MOT test number 353497368439

Result ✓ Passed

MOT #2 2015-04-24 09:34

MOT test number 407964715191

Result ✓ Passed

MOT #1 2015-04-21 12:21

MOT test number 427481515146

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



DN12OZT report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK NIS
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-04-27
Last registration	2022-01-21
Complete history	See info



Registration #1	2012-04-27	28 mi
Registration #2	2015-04-21	22.089 mi
Registration #3	2015-04-24	22.138 mi
Registration #4	2016-03-30	26.636 mi
Registration #5	2017-03-30	30.855 mi
Registration #6	2018-04-12	36.569 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	96%
Children	89%
Pedestrian	49%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1399 mm
Length	4220 mm
Wheel base	2650 mm
Kerb weight	1236 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	4 p.	age 10/10

Number of axles 2

Engine number G4FDBU724579