



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD TYPE S
Colour	Grey
Year of manufacture	2004
Top speed	142 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	188 BHP
Max. torque	220 Nm at 4.500 rpm
Engine capacity	2.354 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	31.4 mpg
CO2 emission	214 g/km
CO2 label	K





MOT history

MOT expiry date	2021-01-17
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	32
Total items failed	2

MOT #16	2020-01-18 08:33
MOT test number	981942967764
Result	✓ Passed
Next expiry date	2021-01-17
Minor	Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #15	2020-01-17 12:00
MOT test number	494727288441
Result	✗ Failed
MAJOR	Windscreen washer not working (3.5 (a))
Minor	Rear Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #14	2018-12-17 14:21
MOT test number	726218759294
Result	✓ Passed

MOT #13	2017-12-05 10:44
MOT test number	764359661360
Result	✓ Passed
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #12**

2016-11-30 08:44

MOT test number

894008358197

Result

✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Central Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #11

2016-11-23 12:11

MOT test number

469950927919

Result

✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement front bush (2.4.G.2)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Nearside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Central Front Brake pad(s) wearing thin (3.5.1g)

**MOT #10**

2015-11-17 11:25

MOT test number

955848491630

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases section (7.1.2)**Advice** Advisory plastic oversills fitted**Advice** Advisory engine cover / under-tray fitted**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Advisory front brake pads wearing low**MOT #9**

2014-11-17 09:45

MOT test number

729321924306

Result

✓ Passed

Advice Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Advisery;plastic oversills fitted**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Tyre worn close to the legal limit (4.1.E.1)**MOT #8**

2013-12-17 14:57

MOT test number

757931153326

Result

✓ Passed

Notice Engine covers fitted obscuring some components in the engine bay**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #7** 2012-11-14 10:59**MOT test number** 197979512334**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Offside and nearside sill covers fitted**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2011-11-29 09:39**MOT test number** 558553431339**Result** ✓ Passed**MOT #5** 2011-02-22 10:39**MOT test number** 437383751065**Result** ✓ Passed**MOT #4** 2010-02-27 10:26**MOT test number** 594118850092**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #3** 2009-02-27 14:56**MOT test number** 383548359053**Result** ✓ Passed**MOT #2** 2008-02-16 09:11**MOT test number** 692107148099**Result** ✓ Passed



MOT #1	2007-02-10 09:13
MOT test number	810141847091
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2004-03-01
Last registration	2020-01-18
Complete history	See info



Registration #1	2004-03-01	29 mi
Registration #2	2007-02-10	34.406 mi
Registration #3	2008-02-16	44.220 mi
Registration #4	2009-02-27	56.163 mi
Registration #5	2010-02-27	69.421 mi
Registration #6	2011-02-22	77.265 mi
Registration #7	2011-11-29	83.682 mi
Registration #8	2012-11-14	87.703 mi
Registration #9	2013-12-17	90.455 mi
Registration #10	2014-01-29	91.377 mi
Registration #11	2014-02-26	91.377 mi
Registration #12	2014-03-26	91.377 mi
Registration #13	2014-04-25	91.377 mi
Registration #14	2014-05-24	91.377 mi
Registration #15	2014-06-23	91.377 mi
Registration #16	2014-07-22	91.377 mi
Registration #17	2014-08-21	91.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1400 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	K24A32011316