



AJ58GBU


report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT SE TDI
Colour	Black
Year of manufacture	2008
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	153 g/km
CO2 label	G





MOT history

MOT expiry date	2020-12-01
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	7
Total items failed	9

MOT #15	2019-11-11 10:38
MOT test number	108673755444
Result	✓ Passed
Next expiry date	2020-12-01

MOT #14	2019-11-11 10:38
MOT test number	641193561152
Result	✗ Failed
Pass with rectification	Front Tyre tread depth below requirements of 1.6mm both (5.2.3 (e))
Pass with rectification	Offside Front Wheel bearing has excessive play (5.1.3 (a) (i))

MOT #13	2018-11-05 12:52
MOT test number	866357343906
Result	✓ Passed

MOT #12	2018-11-05 12:03
MOT test number	867345497416
Result	✗ Failed
MAJOR	Nearside Front Headlamp insecure bracket broken (4.1.1 (c))

**MOT #11** 2017-12-02 10:37**MOT test number** 425841206442**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit Both side (4.1.E.1)**MOT #10** 2017-12-02 10:37**MOT test number** 544630224275**Result** ✗ Failed**Pass with rectification** Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt Both side (2.4.G.2)**Advice** Front Tyre worn close to the legal limit Both side (4.1.E.1)**MOT #9** 2016-12-01 12:44**MOT test number** 665866386903**Result** ✓ Passed**Advice** Offside Front Upper Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt and lower (2.4.G.2)**MOT #8** 2015-09-23 16:04**MOT test number** 363738882253**Result** ✓ Passed**MOT #7** 2015-09-23 12:53**MOT test number** 497105063481**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2014-10-06 15:55**MOT test number** 869109674213**Result** ✓ Passed

**MOT #5** 2014-09-09 15:00**MOT test number** 215012954274**Result** ✗ Failed**Fail** Offside Front Headlamp levelling device obviously defective (1.7.2)**Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (1.9.4)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Headlamp levelling device obviously defective (1.7.2)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2013-09-11 08:25**MOT test number** 407614853273**Result** ✓ Passed**MOT #3** 2012-09-12 13:26**MOT test number** 826506652231**Result** ✓ Passed**MOT #2** 2012-09-12 13:26**MOT test number** 216516952298**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**MOT #1** 2011-09-01 12:27**MOT test number** 886374541291**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 December 2020

✕
MOT

Expired:
1 December 2020

Tax status	Expired at 1 December 2020
Days left	1245 days too late
MOT expiry date	1 December 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-09-12
Last registration	2019-11-11
Complete history	See info



Registration #1	2008-09-12	29 mi
Registration #2	2011-09-01	30.439 mi
Registration #3	2012-09-12	40.962 mi
Registration #4	2013-09-11	48.445 mi
Registration #5	2014-09-09	57.638 mi
Registration #6	2014-10-06	57.657 mi
Registration #7	2015-09-23	66.049 mi
Registration #8	2015-09-23	66.062 mi
Registration #9	2016-09-23	75.277 mi
Registration #10	2017-09-23	84.492 mi
Registration #11	2018-09-23	93.707 mi
Registration #12	2019-09-23	102.922 mi
Registration #13	2020-09-23	112.137 mi
Registration #14	2021-09-23	121.352 mi
Registration #15	2022-09-23	130.567 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 056163