



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA S
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-18
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT #18 2022-03-16 17:21

MOT test number 873211318130

Result ✗ Failed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside door mirror cover missing
- Fail** Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced front cross member holed and corroded (6.1.1 (c) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside door mirror cover missing
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #17** 2021-02-17 16:40**MOT test number** 850176685660**Result** ✓ Passed

- Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear suspension components corroded
- Advice** Offside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** N/s front bumper, n/s rear quarter panel and o/s rear bumper dented or scuffed
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside sill damaged (long Dent)

**MOT #16** 2019-06-12 12:28**MOT test number** 135050083382**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15** 2018-07-05 14:25**MOT test number** 343787294429**Result** ✓ Passed

**MOT #14** 2018-07-05 11:50**MOT test number** 121989589633**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2017-07-13 14:33**MOT test number** 837751651300**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2017-07-13 11:23**MOT test number** 215086430566**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2016-07-01 12:32**MOT test number** 794384449099**Result** ✓ Passed**Advice** Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear tyre showing signs of ageing and deterioration**Advice** Nearside Front wiper split**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear tyre showing signs of aging and deterioration

**MOT #10** 2015-07-03 11:55**MOT test number** 457054285141**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-06-24 11:18**MOT test number** 379695374179**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2013-07-15 15:51**MOT test number** 408926293173**Result** ✓ Passed**MOT #7** 2012-07-16 10:20**MOT test number** 295868692481**Result** ✓ Passed**MOT #6** 2011-06-09 10:15**MOT test number** 437280061195**Result** ✓ Passed**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**MOT #5** 2010-06-24 13:41**MOT test number** 673235070131**Result** ✓ Passed

**MOT #4** 2009-06-17 12:46**MOT test number** 231488069140**Result** ✓ Passed**Advice** Power steering pump has slight seepage from a component (2.3.3b)**MOT #3** 2008-06-05 09:39**MOT test number** 152147958190**Result** ✓ Passed**Notice** Oil leak**MOT #2** 2007-06-08 14:26**MOT test number** 854169157121**Result** ✓ Passed**MOT #1** 2006-06-24 10:16**MOT test number** 821115176141**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history


Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2003-06-25
Last registration	2022-03-16
Complete history	<a href="#">See info</a>



Registration #1	2003-06-25	16 mi
Registration #2	2006-06-24	26.584 mi
Registration #3	2007-06-08	32.028 mi
Registration #4	2008-06-05	34.019 mi
Registration #5	2009-06-17	35.709 mi
Registration #6	2010-06-24	37.276 mi
Registration #7	2011-06-09	38.304 mi
Registration #8	2012-07-16	39.144 mi
Registration #9	2013-07-15	39.603 mi
Registration #10	2014-06-24	40.017 mi
Registration #11	2015-06-24	39.999 mi
Registration #12	2016-06-24	39.999 mi
Registration #13	2017-06-24	39.999 mi
Registration #14	2018-06-24	39.999 mi
Registration #15	2019-06-24	39.999 mi
Registration #16	2020-06-24	39.999 mi
Registration #17	2021-06-24	39.999 mi
Registration #18	2022-03-16	39.999 mi
Registration #19	2023-03-16	39.999 mi
Registration #20	2024-03-16	39.999 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	197826