



LB09BJF

report date: 2024-03-28

General information

Make	FIAT
Model	DUCATO 30SWB 100 MULTIJET P/V
Colour	White
Year of manufacture	2009
Top speed	87 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel




LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-13
Pictures	1
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-13
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-27
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	9
Total items failed	21

MOT #20	2023-11-24 15:46
MOT test number	717517496847
Result	✓ Passed
Next expiry date	2024-11-27

MOT #19	2023-11-24 09:35
MOT test number	445722573759
Result	✗ Failed
Fail	Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Inner Seat belt anchorage prescribed area strength or continuity significantly reduced Sill area (7.1.1 (a) (i))

MOT #18	2022-11-28 16:45
MOT test number	876180693178
Result	✓ Passed
Advice	Rear Springs on bump stops
Advice	Offside Park brake poor

**MOT #17** 2022-11-28 09:20**MOT test number** 411000750864**Result** ✗ Failed**Advice** Rear Springs on bump stops**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Park brake poor**Fail** Front Exhaust has a major leak of exhaust gases Pipe broken (6.1.2 (a))**MOT #16** 2022-01-28 16:33**MOT test number** 394380832642**Result** ✓ Passed**MOT #15** 2022-01-28 09:07**MOT test number** 680013633097**Result** ✗ Failed**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Fuel system component leaking Filter housing. (6.1.3 (b) (i))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner Sill, adjacent to spring mount. (5.3.6 (a) (i))**Fail** Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**MOT #14** 2021-01-29 08:13**MOT test number** 499432346909**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #13** 2020-01-28 08:57**MOT test number** 269742703835**Result** ✓ Passed**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**MOT #12** 2019-01-23 15:45**MOT test number** 623733853819**Result** ✓ Passed**MOT #11** 2019-01-23 10:17**MOT test number** 783061065060**Result** ✗ Failed**Fail** Nearside Rear Inner Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Sill (5.3.6 (a) (i))**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**MOT #10** 2018-01-29 09:00**MOT test number** 879687381245**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #9** 2017-01-27 15:42**MOT test number** 841785882100**Result** ✓ Passed

**MOT #8** 2017-01-27 08:53**MOT test number** 872097284669**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front Exhaust has a major leak of exhaust gases flex (7.1.2)**MOT #7** 2016-01-29 15:46**MOT test number** 407368649944**Result** ✓ Passed**MOT #6** 2016-01-29 09:22**MOT test number** 625640873357**Result** ✗ Failed**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2015-01-30 17:10**MOT test number** 186700435011**Result** ✓ Passed**MOT #4** 2015-01-29 13:50**MOT test number** 196019725044**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)**Fail** Exhaust system not adequately supported (7.1.1)**MOT #3** 2014-03-07 14:38**MOT test number** 788306164052**Result** ✓ Passed



MOT #2	2013-03-28 13:42
MOT test number	229537283069
Result	✓ Passed
MOT #1	2012-03-19 13:29
MOT test number	645839572027
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
27 November 2024

Tax status	Valid until 1 December
-------------------	------------------------

Days left	217
------------------	-----

MOT expiry date	27 November 2024
------------------------	------------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	LB09BJF
Plate since	2024-03-28
Current registration	LB09BJF
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-07-22
Last registration	2023-11-24
Complete history	See info



Registration #1	2009-07-22	15 mi
Registration #2	2012-03-19	10.521 mi
Registration #3	2013-03-28	17.163 mi
Registration #4	2014-03-07	22.935 mi
Registration #5	2015-01-29	27.343 mi
Registration #6	2015-01-30	27.363 mi
Registration #7	2016-01-29	34.645 mi
Registration #8	2016-01-29	34.647 mi
Registration #9	2017-01-27	41.522 mi
Registration #10	2017-01-27	41.522 mi
Registration #11	2018-01-29	51.066 mi
Registration #12	2019-01-23	60.318 mi
Registration #13	2019-01-23	60.318 mi
Registration #14	2019-01-23	60.318 mi
Registration #15	2019-01-23	60.318 mi
Registration #16	2019-01-23	60.318 mi
Registration #17	2019-01-23	60.318 mi
Registration #18	2019-01-23	60.318 mi
Registration #19	2019-01-23	60.318 mi
Registration #20	2019-01-23	60.318 mi
Registration #21	2019-01-23	60.318 mi
Registration #22	2019-01-23	60.318 mi
Registration #23	2019-01-23	60.318 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	0276002