




report date: 2024-03-28

General information

Make	NISSAN
Model	350 Z V6
Colour	Silver
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	276 BHP
Max. torque	363 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	17.5 mpg
Consumption extra urban	32.5 mpg
Consumption combined	24.8 mpg
CO2 emission	273 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-09-15
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-20
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	49
Total items failed	4

MOT #20 2023-06-21 14:24

MOT test number 385159307197

Result ✓ Passed

Next expiry date 2024-06-20

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Front Headlamp lens deteriorated but light output not reduced (1.7.4a)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner and outer edges. (5.2.3 (e))
- Advice** Nearside Front Headlamp lens deteriorated but light output not reduced (1.7.4a)
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner and outer edges. (5.2.3 (e))

MOT #19 2022-06-08 14:01

MOT test number 401364628507

Result ✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** 16%) Parking Brake: parking brake efficiency only just met. It would appear the braking system requires adjustment or repair. [3.7.A.7]

MOT #18 2021-06-18 13:02

MOT test number 527375861509

Result ✓ Passed

**MOT #17**

2021-01-20 09:58

MOT test number

397724083924

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16**

2020-01-04 10:10

MOT test number

924432879934

Result

✓ Passed

Advice Offside Front Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Central Inner Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #15**

2019-01-16 16:56

MOT test number

524752713178

Result

✓ Passed

Advice Corrosion forming on,nr suspension ,front and rear**MOT #14**

2018-12-28 09:34

MOT test number

751018081924

Result

✗ Failed

Advice Handbrake travel long**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn inner (5.3.4 (a) (i))

**MOT #13** 2017-12-27 12:21**MOT test number** 665903194443**Result** ✓ Passed**MOT #12** 2016-10-05 09:34**MOT test number** 646523895637**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (3.5.1i)**MOT #11** 2015-08-05 14:21**MOT test number** 327687515437**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2015-08-05 14:21**MOT test number** 187847615249**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #9** 2014-07-03 14:02**MOT test number** 526814384148**Result** ✓ Passed

- Notice** Rear tyres on 2mm
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8 2014-07-01 17:30**MOT test number** 205292084495**Result** ✗ Failed

- Notice** Rear tyres on 2mm
- Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2013-06-29 10:22**MOT test number** 736070983144**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2012-06-13 12:21**MOT test number** 599055762181**Result** ✓ Passed**Notice** Front brake discs pitted**Notice** Front number plate deteriorating**MOT #5** 2011-05-10 13:30**MOT test number** 466410131110**Result** ✓ Passed**MOT #4** 2010-06-10 14:25**MOT test number** 212421860477**Result** ✓ Passed**MOT #3** 2010-06-02 16:21**MOT test number** 471673350196**Result** ✗ Failed**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc slightly pitted (3.5.1h)



MOT #2	2010-03-02 14:25
MOT test number	143731060054
Result	✓ Passed
Advice	Rear brake disc slightly scored (3.5.1h)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc slightly pitted (3.5.1h)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-03-12 11:34
MOT test number	762001079000
Result	✓ Passed



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-03-15
Last registration	2023-06-21
Complete history	See info



Registration #1	2006-03-15	22 mi
Registration #2	2009-03-12	13.070 mi
Registration #3	2010-03-02	15.680 mi
Registration #4	2010-06-02	16.714 mi
Registration #5	2010-06-10	16.714 mi
Registration #6	2011-05-10	20.277 mi
Registration #7	2012-06-13	27.389 mi
Registration #8	2013-06-29	32.116 mi
Registration #9	2014-07-01	36.727 mi
Registration #10	2014-07-03	36.771 mi
Registration #11	2015-08-05	44.665 mi
Registration #12	2016-06-20	51.277 mi
Registration #13	2017-06-20	58.277 mi
Registration #14	2018-06-20	65.277 mi
Registration #15	2019-06-20	72.277 mi
Registration #16	2020-06-20	79.277 mi
Registration #17	2021-06-20	86.277 mi
Registration #18	2022-06-20	93.277 mi
Registration #19	2023-06-20	100.277 mi
Registration #20	2023-06-20	107.277 mi
Registration #21	2023-06-20	114.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1547 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	602817