





report date: 2024-03-29

## General information

Make	MINI
Model	COOPER D ONE D
Colour	Red
Year of manufacture	2013
Top speed	114 mph
0 - 60 mph	11.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	А



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 1

Date 2022-02-05

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

	~		
10/1/	<b>1</b>	hic	tory
- 1010	,, ,	1115	IUIV
	<i>-</i> .		

MOT expiry date	2025-03-07
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	13
Total items failed	4

MOT #12	2024-03-05 15:13
MOT test number	793673455081
Result	<b>✓</b> Passed
Next expiry date	2025-03-07

MOT #11	2024-03-01 09:55	
MOT test number	462353548514	
Result	<b>X</b> Failed	
Advice Offside Rear Tyre slightly damaged/cracking or perishing centre of tread (5.2.3 (d) (ii))		
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Fail Nearside Rear Tyre has ply or cords exposed centre of tread (5.2.3 (d) (ii))		

MOT #10	2023-03-03 16:20
MOT test	number 756345529824
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing in centre of tread (5.2.3 (d) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge of tread (5.2.3 (e))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #9		2023-03-03 11:46
MOT test	number	163927996868
Result		<b>X</b> Failed
Advice Offside Front Tyre slightly damaged/cracking or perishing in centre of tread (5.2.3 (d) (ii))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge of tread (5.2.3 (e))		
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))		

MOT #8	2022-03-08 16:08
MOT test number	667591857840
Result	<b>✓</b> Passed
MOT #7	2021-04-20 08:51
MOT test number	686626531513
Result	<b>✓</b> Passed
MOT #6	2020-03-27 09:57
MOT test number	453734765334
Result	<b>✓</b> Passed
MOT #5	2019-04-16 11:04
MOT test number	496325046487

MOT #5	2019-04-16 11:04
MOT test number	496325046487
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4		2018-04-20 12:22
MOT test	number	624893401700
Result		✓ Passed
Advice	Nearside Rear Tyre Cracking On Edges	
Advice	Offside Front Tyre worn close to the legal limit 175/65/15 @ 3mm (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit 175/65/15 @ 3mm (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit 175/65/15 @ 3mm (4.1.E.1)	
Advice	Offside Rear Tyre Cracking On Edges	
Advice	Nearside Rear Tyre worn close to the legal limit 175/65/15 @ 3mm (4.1.E.1)	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3	2017-04-27 10:53
MOT test number	818559096126
Result	<b>✓</b> Passed
MOT #2	2016-09-15 09:43
MOT test number	369644040141
Result	./ Passed

MOT #1	2016-09-14 11:14
MOT test number	122831962998
Result	<b>X</b> Failed
Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)  Fail Nearside Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 5/12



report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	7 March 2025
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	UK JIN
Flate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-07-26
Last registration	2024-03-05
Complete history	See info



Registration #1	2013-07-26	28 mi
Registration #2	2016-09-14	46.338 mi
Registration #3	2016-09-15	46.339 mi
Registration #4	2017-04-27	46.380 mi
Registration #5	2018-04-20	47.793 mi
Registration #6	2019-04-16	48.901 mi
Registration #7	2020-03-27	51.179 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.177 es
Registration #13		11.777 es

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

## Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	4 page 1	2/12

Number of axles 2

**Engine number** 70728575