





report date: 2024-03-28

General information

Make	TOYOTA
Model	IQ VVT-I IQ
Colour	Black
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-28

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-04-19
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	19
Total items failed	7

MOT #15	2023-04-20 08:49
MOT test number	500643192730
Result	✓ Passed
Next expiry date	2024-04-19
Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))	
Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	

MOT #14		2022-04-08 09:40
MOT test	number	308366807030
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #13	2022-04-08 09:40	
MOT test number	312366857294	
Result	★ Failed	
Pass with rectification	Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Pass with rectification	Offside Windscreen washer provides insufficient washer liquid (3.5 (a))	

CarCheck.co.uk page 3/13



Result

GU59ZHN

report date: 2024-03-28

Passed

MOT #12 2021-04-06 13:45

MOT test number 881028461556

Result ✓ Passed

Advice Steering suspension and brake system components all covered in grease or other material

MOT #11 2020-08-13 16:01

MOT test number 433554391308

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2020-08-13 10:10

MOT test number 174858758531

Result × Failed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

Fail Front Windscreen wiper does not clear the windscreen effectively BOTH (3.4 (b) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Perished (5.2.3 (d) (ii))

MOT #9 2019-06-05 12:05

MOT test number 956305780887

Result
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

✓ Passed

MOT #8 2019-06-05 08:20

MOT test number 711839606643

Result × Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2018-06-26 08:42

MOT test number 797718681693

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2017-06-09 10:34

MOT test number 739681528395

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #5 2016-06-07 11:29

MOT test number 154412707915

Advice Offside Front tyre cracking and small cut in tread

Advice Nearside Front tyre cracking

Result

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4 2016-06-07 09:39 **MOT test number** 456111785633 Result **X** Failed **Advice** Offside Front tyre cracking and small cut in tread Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Headlamp aim too low (1.8) Advice Nearside Front tyre cracking Nearside Headlamp aim too low (1.8) Fail

MOT #3	2015-03-19 09:38
MOT test number	739548475064
Result	✓ Passed
Notice N/s/r and o/s/r tyres cracking	

MOT #2	2013-09-20 17:12
MOT test number	308173763288
Result	✓ Passed
MOT #1	2012-09-20 13:41
MOT test number	417824162289
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	19 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

_	
Owner	hictory
OWITE	HIISLUH V

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	NK NY
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-10-14
Last registration	2023-04-20
Complete history	See info



Registration #1	2009-10-14	24 mi
Registration #2	2012-09-20	28.642 mi
Registration #3	2013-09-20	34.357 mi
Registration #4	2015-03-19	39.736 mi
Registration #5	2016-06-07	43.598 mi
Registration #6	2016-06-07	43.598 mi
Registration #7	2017-06-09	47.155 mi
Registration #8	2018-06-26	50.771 mi
Registration #9	2019-06-05	53.974 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	845 kg
Max. allowed weight	1215 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 1KR0827053