





report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOVANO F3500 L2H1 C/C CDTI S/S
Colour	White
Year of manufacture	2016
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	2.299 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	35.0 mpg
Consumption combined	34.0 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 2

Date 2022-03-04

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-10-27
------	------------

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-02-23
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	20
Total items failed	4

MOT #8	2024-02-12 10:05
MOT test number	629740688721
Result	✓ Passed
Next expiry date	2025-02-23
Minor Offside All direction indicators flashing more than 120 times a minute Advice Rear Parking brake efficiency only just met. It would appear that the	
adjustment or repair. (1.4.2 (a) (i))	braking system requires
Advice Rear Service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.2.2 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i	ii))

MOT #7	2023-02-22 15:41
MOT test number	826923576051
Result	✓ Passed

MOT #6	2023-02-22 13:36
MOT test number	964311778701
Result	× Failed
Fail Offside Front Side repeater incorrect colour (4.4.3 (a))	
Fail Nearside Front Headlamp aim too low (4.1.2 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2022-02-24 15:45 **MOT** test number 303086321569 ✓ Passed Result **Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Minor Nearside Front Direction indicator flashing more than 120 times a minute (4.4.4 (a))

MOT #4 2022-02-24 15:45 **MOT** test number 323560492091 Result × Failed **Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Minor Nearside Front Direction indicator flashing more than 120 times a minute (4.4.4 (a)) Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))


Minor Nearside Front Direction indicator flashing more than 120 times a minute (4.4.4 (a))

Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



report date: 2024-03-28



 MOT #1
 2019-12-06 11:39

 MOT test number
 620716900265

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	23 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	

2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NK UK
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-01-18
Last registration	2024-02-12
Complete history	See info



Registration #1	2016-01-18	9 mi
Registration #2	2019-12-06	43.313 mi
Registration #3	2021-01-21	59.005 mi
Registration #4	2021-01-21	59.005 mi
Registration #5		11.777 es
Registration #6	2022-02-24	69.177 mi
Registration #7		11.777 es
Registration #8		77,777 46
Registration #9		71.777 66
Registration #10		71,777 66
Registration #11		71.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2070 mm
Height	2258 mm
Length	5643 mm
Wheel base	3682 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	M9T -C014293 L0C

CarCheck.co.uk page 12/12