



report date: 2024-03-29

General information

Make	KIA
Model	VENGA 2
Colour	Black
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 4

Date	2022-09-03
Pictures	7
Listing price	View report



source: cargurus.co.uk

Entry 3

Date	2021-11-22
Pictures	6
Listing price	View report



source: yesauto.com

Entry 2

Date	2021-11-19
Pictures	6
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-15
------	------------

Pictures

4

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-01
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	8
Total items failed	3

MOT #8	2024-01-17 09:09
MOT test number	534561864295
Result	✓ Passed
Next expiry date	2025-02-01

MOT #7	2023-02-02 13:01
MOT test number	136300204050
Result	✓ Passed

MOT #6	2023-02-02 13:01
MOT test number	487183822988
Result	✗ Failed

- Pass with rectification Offside Headlamp aim too high (4.1.2 (a))
- Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))
- Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #5	2021-12-23 16:28
MOT test number	140212141646
Result	✓ Passed

**MOT #4** 2020-06-05 08:52**MOT test number** 122670110044**Result** ✓ Passed**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2019-04-25 11:21**MOT test number** 645258089359**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Nail in tyre**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2** 2018-05-21 09:20**MOT test number** 732869795341**Result** ✓ Passed**MOT #1** 2017-12-07 15:15**MOT test number** 733289288435**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	YW64BVE
Plate since	2024-03-29
Current registration	YW64BVE
Plate since	2024-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-02-18
Last registration	2024-01-17
Complete history	See info



Registration #1	2015-02-18	25 mi
Registration #2	2017-12-07	15.681 mi
Registration #3	2018-05-21	16.815 mi
Registration #4	2019-04-25	22.636 mi
Registration #5	2020-06-05	27.331 mi
Registration #6	2020-06-05	27.331 mi
Registration #7	2020-06-05	27.331 mi
Registration #8	2020-06-05	27.331 mi
Registration #9	2020-06-05	27.331 mi
Registration #10	2020-06-05	27.331 mi
Registration #11	2020-06-05	27.331 mi
Registration #12	2020-06-05	27.331 mi
Registration #13	2020-06-05	27.331 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4075 mm
Wheel base	2615 mm
Kerb weight	1369 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FCEZ341712