

Ford



## General information

Make	FORD
Model	C-MAX ZETEC TDCI
Colour	Blue
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С





## Internet history

Entry 1

Date

Pictures

2021-10-21

7

Listing price

View report



source: autotrader.co.uk



## MOT history

MOT expiry date	2023-03-04
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #13	2022-03-05 11:46
MOT test number	543492446968
Result	✓ Passed
Next expiry date	2023-03-04
Minor Nearside Registration plate lamp inoperative in the case of multiple la (b) (i))	amps or light sources (4.7.1

MOT #12	2021-02-11 15:17
MOT test number	225191420341
Result	✓ Passed

MOT #11	2021-02-04 09:33
MOT test number	529908263712
Result	🗙 Failed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Fail         Offside Registration plate lamp inoperative in the case of a single lamp or all la	mps (4.7.1 (b) (ii))
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excess (a) (i))	ive movement (5.3.4



MOT #10	2020-02-21 11:02
MOT test number	495401298523
Result	Passed
AdviceFront Upper Coil spring worn both sides (5.3.1 (b) (i))AdviceOffside Rear brakes binding/pads low	

МОТ #9	2019-02-18 09:35
MOT test number	617895795335
Result	✓ Passed

MOT #8	2018-02-23 11:17
MOT test number	416400870365
Result	✓ Passed
Advice Nearside Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #7	2017-10-26 12:46
MOT test number	593103973844
Result	✓ Passed

MOT #6	2017-10-26 12:35
MOT test number	107714782096
Result	🗙 Failed
<b>Fail</b> Brake pedal anti-slip provision missing (3.3.A.1b)	

SP59LGW

report date: 2024-03-28



MOT #5		2016-10-29 11:20
MOT test	number	540951362360
Result		✓ Passed
Advice	Oil leak	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice	Rear brake pads look 75% worn	
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	

МОТ #4	2015-10-29 10:48
MOT test number	451134844929
Result	✓ Passed
Advice Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)	
Advice Child seat fitted not allowed full inspection of adult belt	
Advice Front coil spring corroded N/S/F & O/S/F (2.4.C.1b)	

MOT #3		2014-10-22 10:51
MOT test	number	925005494202
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Child seat fitted not allowing full inspection of adult belt	





MOT #2		2013-10-29 11:13
MOT test	number	607402203349
Result		✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	
MOT #1		2012-10-04 16:57
MOT test	number	908918172212

 Result

 ✓ Passed

 Notice
 Nail in offside rear tyre



Tax & MOT check

X Untaxed Tax expired: 30 November 2022	<b>X</b> <b>MOT</b> <b>Expired:</b> 4 March 2023
Tax status	Expired at 30 November 2022
Days left	516 days too late
MOT expiry date	4 March 2023
Full MOT history	See MOT history
Tax calculation	
Vehicle class	49
Band	С

Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	 
Category	 AMPL
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	
***********	
********	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Carrent registration Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 



SP59LGW report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-10-28
Last registration	2022-03-05
Complete history	See info



Registration #1	2009-10-28	7 mi
Registration #2	2012-10-04	80.485 mi
Registration #3	2013-10-29	89.360 mi
Registration #4	2014-10-22	97.956 mi
Registration #5	2015-10-29	111.778 mi
Registration #6	2016-10-29	122.976 mi
Registration #7	2017-10-26	132.513 mi
Registration #8	2017-10-26	132.513 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi

More info >





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg
Additional information	
Fuel delivery	Direct Injection

ruei ueilvery	Direct injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13