





report date: 2024-03-28

### General information

| Make                | CITROEN        |
|---------------------|----------------|
| Model               | DS5 HDI DSTYLE |
| Colour              | Blue           |
| Year of manufacture | 2012           |
| Top speed           | 134 mph        |
| 0 - 60 mph          | 8.5 seconds    |
| Gearbox             | 6 speed Manual |

## Engine & fuel consumption

| Power                   | 161 BHP             |
|-------------------------|---------------------|
| Max. torque             | 340 Nm at 2.000 rpm |
| Engine capacity         | 1.997 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 44.8 mpg            |
| Consumption extra urban | 68.9 mpg            |
| Consumption combined    | 57.7 mpg            |
| CO2 emission            | 133 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/13



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-12-09


Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

## MOT history

| MOT expiry date    | 2025-01-31 |
|--------------------|------------|
| MOT pass rate      | 77 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 3          |
| Total advice items | 24         |
| Total items failed | 0          |

| MOT #13  |  | 2024-01-17 13:05 |
|--|--|------------------|
| MOT test   | number   | 542671212815     |
| Result   |  | ✓ Passed         |
| Next expi  | ry date  | 2025-01-31       |
| Advice Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i)) |  |                  |
| Advice   | Nearside Rear Child Seat fitted not allowing full inspection of adult belt |                  |

| MOT #12   |  | 2024-01-15 15:40 |
|---|--|------------------|
| MOT test  | number   | 935037922820     |
| Result  |  | <b>×</b> Failed  |
| Advice  | Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i) | ))               |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt |  |                  |
| <b>DANGEROUS</b> Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))       |  |                  |
| <b>Minor</b> (b) (i))   | Nearside Registration plate lamp inoperative in the case of multiple lamps or ligh | t sources (4.7.1 |
| Advice  | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                                  |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MOT test number

210619421466

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

MAJOR

Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Minor

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

| MOT #9          | 2021-12-13 12:39 |
|-----------------|------------------|
| MOT test number | 418868564947     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #8          | 2021-01-04 15:54 |
| MOT test number | 246948541968     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #7          | 2020-01-03 16:19 |
| MOT test number | 938353523191     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

347492828221

Result

Advice Offside Front Tyre worn close to legal limit/worn on edge Worn to limit (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn to limit (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #5** 2018-09-19 07:05 **MOT** test number 848168932366 Result ✓ Passed **MOT #4** 2018-09-17 10:23 **MOT** test number 679560221518 Result × Failed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3

MOT test number

Fesult

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2

MOT test number

835137651089

Result

✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Advice Engine Covers & Undertrays Fitted Obscuring Some Components

Advice Emissions Level To Low To Recieve Data

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 January |
|------------------|-----------------------|
| Days left        | 247                   |
| MOT expiry date  | 31 January 2025       |
| Full MOT history | See MOT history       |

### Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

| Ow     |     | la : - |  |
|--------|-----|--------|--|
| ( )\// | ner | nısı   |  |
|        |     |        |  |

| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full in |             | ΞN |
|---|-------------|----|
|   |             |    |
|   |             |    |
|   |             |    |
| ***************************************   |             |    |
|   |             |    |
|   |             |    |
|   |             |    |
|   |             |    |
|   |             |    |
|   | More info > |    |
| Plate changes   |             |    |
| See in this check if this CITROEN had different number plates.  |             |    |
| Number of plates  |             |    |
| Current registration  | UK UK       |    |
| Plate since   |             |    |
| Current registration  | UK C        |    |
| Plate since   |             |    |
|   | More info > |    |

CarCheck.co.uk page 10/13



report date: 2024-03-28

### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 15         |
| First mileage registration | 2012-09-24 |
| Last registration          | 2024-01-17 |
| Complete history           | See info   |



| Registration #1  | 2012-09-24 | 14 mi     |
|------------------|------------|-----------|
| Registration #2  | 2015-09-01 | 23.886 mi |
| Registration #3  | 2016-09-29 | 34.627 mi |
| Registration #4  | 2017-09-09 | 42.297 mi |
| Registration #5  | 2018-09-17 | 48.730 mi |
| Registration #6  | 2018-09-19 | 48.738 mi |
| Registration #7  | 2019-10-17 | 58.387 mi |
| Registration #8  | 2020-01-03 | 58.906 mi |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 9.70 es   |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 9.70 es   |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 70,777 es |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 89%             |
| Children       | 83%             |
| Pedestrian     | 40%             |
| Safety systems | 97%             |
| Overall rating | 79%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1850 mm |
|---------------------|---------|
| Height              | 1508 mm |
| Length              | 4530 mm |
| Wheel base          | 2727 mm |
| Kerb weight         | 1540 kg |
| Max. allowed weight | 2130 kg |

## Additional information

| Fuel tank capacity | 60 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | DYZE4032519      |

CarCheck.co.uk page 13/13