





report date: 2024-03-28

General information

Make	BMW
Model	123 123D M SPORT
Colour	Black
Year of manufacture	2010
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	201 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	135 g/km
CO2 label	Е



CarCheck.co.uk page 1/13



report date: 2024-03-28


Internet history

Entry 1

Date 2021-10-11

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-03-31
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	16
Total items failed	7

MOT #13	2024-03-26 15:53
MOT test number	354266229218
Result	✓ Passed
Next expiry date	2025-03-31
Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting i inner bush (5.3.4 (a) (i))	n excessive movement
Advice Nearside Front Tyre worn close to legal limit/worn on edge outer edge v	vear (5.2.3 (e))
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting inner bush (5.3.4 (a) (i))	g in excessive movement
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2023-03-27 14:14
MOT test number	313446374854
Result	✓ Passed
Advice Offside Rear Upper Suspension arm pin or bush worn but not resulting in Rear most, upper suspension arm, outer pin. (5.3.4 (a) (i))	n excessive movement
Advice Nearside Rear Upper Suspension arm pin or bush worn but not resulting Rear most, upper suspension arm outer pin. (5.3.4 (a) (i))	in excessive movement
Minor Nearside Front Lower Suspension arm ball joint dust cover severely deterarm. Outer ball joint. (5.3.4 (b) (i))	riorated Front most lower

CarCheck.co.uk page 3/13



report date: 2024-03-28

× Failed

MOT #11 2022-04-01 14:29

MOT test number 747679151573

Result ✓ Passed

Advice

Result

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2022-03-30 13:41

MOT test number 277320105995

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #9 2021-03-19 11:27

MOT test number 286038136117

Result

Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Covers not allowing full inspection

CarCheck.co.uk page 4/13



Advice

Brake pad(s) wearing thin (3.5.1g)

M88RDS report date: 2024-03-28

MOT #8 2021-03-12 09:13 254306712189 **MOT test number** Result × Failed Fail Windscreen washer provides insufficient washer liquid (3.5 (a)) Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) Advice Covers not allowing full inspection Fail Rear Direction indicator incorrect colour Both sides (4.4.3 (a)) Offside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Fail Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))	
MOT #7	2020-03-13 12:39
MOT test number	738182014291
Result	✓ Passed
MOT #6	2019-03-15 10:58
MOT test number	501879503389
Result	✓ Passed
MOT #5	2018-03-23 11:10
MOT test number	685937450382
Result	✓ Passed
MOT #4	2016-11-16 13:10
MOT test number	644198620675
Result	✓ Passed

CarCheck.co.uk page 5/13



Result

M88RDS report date: 2024-03-28

✓ Passed

MOT #3	2015-11-07 11:34
MOT test number	352539293164
Result	✓ Passed
MOT #2	2014-11-05 10:44
MOT test number	708469404392
Result	✓ Passed
MOT #1	2013-10-14 17:23
MOT test number	539347783203

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	31 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-11-10
Last registration	2024-03-26
Complete history	See info



Registration #1	2010-11-10	17 mi
Registration #2	2013-10-14	22.963 mi
Registration #3	2014-11-05	37.518 mi
Registration #4	2015-11-07	58.033 mi
Registration #5	2016-11-16	63.631 mi
Registration #6	2018-03-23	70.592 mi
Registration #7	2019-03-15	73.895 mi
Registration #8	2020-03-13	80.291 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1748 mm
Height	1423 mm
Length	4360 mm
Wheel base	2660 mm
Kerb weight	1420 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 13/1

Number of axles 2
Engine number 87517619