



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI ALTITUDE
Colour	Silver
Year of manufacture	2009
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	19.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	26.9 mpg
CO2 emission	278 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-08-07
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-12
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	47
Total items failed	13

MOT #21	2023-05-05 13:10
MOT test number	649955455943
Result	✓ Passed
Next expiry date	2024-05-12
Advice	Rear Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))

MOT #20	2023-05-03 11:24
MOT test number	752536347877
Result	✗ Failed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Brake hose excessively deteriorated (1.1.12 (b) (ii))
Advice	Rear Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i))
Fail	Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**MOT #19**

2022-05-13 12:20

MOT test number

533145364972

Result

✓ Passed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #18

2022-05-12 16:08

MOT test number

138127395988

Result

✗ Failed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Fuel cap/sealing device missing (6.1.3 (b) (i))

MOT #17

2021-11-11 14:44

MOT test number

714905418078

Result

✓ Passed

- Advice** Nearside Front Inner Play in steering rack inner joint(s)
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))

**MOT #16** 2021-11-11 10:18**MOT test number** 855117371084**Result** ✗ Failed**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Front Inner Play in steering rack inner joint(s)**Fail** Fuel cap/sealing device missing (6.1.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Fail** Offside Rear Service brake grabbing severely (1.2.1 (c))**MOT #15** 2020-09-30 07:40**MOT test number** 698817216275**Result** ✓ Passed**Advice** Nearside Front steering rack end slight play**Advice** Nearside Front link bar slight play**MOT #14** 2019-08-27 07:26**MOT test number** 254262344299**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #13** 2018-10-03 15:25**MOT test number** 893050760361**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #12**

2018-09-28 09:29

MOT test number

725303718817

Result

✗ Failed

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11

2017-12-12 11:07

MOT test number

413858130058

Result

✓ Passed

Advice

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear of front (2.4.G.2)

Advice

Plastic under trays fitted

Advice

Plastic engine cover fitted

MOT #10

2017-12-11 11:54

MOT test number

888794259770

Result

✗ Failed

Fail

Offside Front coil spring broken (2.4.C.1a)

Advice

Plastic under trays fitted

Fail

Offside Rear coil spring broken (2.4.C.1a)

Advice

Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear of front (2.4.G.2)

Advice

Plastic engine cover fitted

**MOT #9** 2016-12-31 10:52**MOT test number** 395894851226**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #8** 2016-12-31 10:15**MOT test number** 185734644592**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Offside Front Tyre badly worn on inner edge**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit 3mm (4.1.E.1)**MOT #7** 2015-12-19 10:50**MOT test number** 818189841547**Result** ✓ Passed**MOT #6** 2015-12-18 11:43**MOT test number** 946133606086**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2015-01-22 10:55**MOT test number** 757302825085**Result** ✓ Passed



MOT #4	2015-01-19 16:44
MOT test number	338339715046
Result	✗ Failed
Fail	Nearside Front Mechanical brake component has restricted free movement (3.5.1k)

MOT #3	2014-01-27 12:22
MOT test number	249277924097
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2	2013-02-01 12:03
MOT test number	858722233073
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2012-02-01 11:37
MOT test number	489162032009
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
12 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-02-06
Last registration	2023-05-05
Complete history	See info



Registration #1	2009-02-06	25 mi
Registration #2	2012-02-01	11.592 mi
Registration #3	2013-02-01	20.459 mi
Registration #4	2014-01-27	32.734 mi
Registration #5	2015-01-19	45.936 mi
Registration #6	2015-01-22	45.936 mi
Registration #7	2015-12-18	59.917 mi
Registration #8	2015-12-19	59.917 mi
Registration #9	2016-12-31	78.698 mi
Registration #10	2016-12-31	78.698 mi
Registration #11	2017-12-11	90.799 mi
Registration #12	2017-12-12	90.802 mi
Registration #13	2018-05-20	91.277 mi
Registration #14	2018-05-20	91.277 mi
Registration #15	2018-05-20	91.277 mi
Registration #16	2018-05-20	91.277 mi
Registration #17	2018-05-20	91.277 mi
Registration #18	2018-05-20	91.277 mi
Registration #19	2018-05-20	91.277 mi
Registration #20	2018-05-20	91.277 mi
Registration #21	2018-05-20	91.277 mi
Registration #22	2018-05-20	91.277 mi
Registration #23	2018-05-20	91.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Kerb weight	2530 kg
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BKS 083131