



report date: 2024-03-29

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Red
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-13
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	40
Total items failed	19

MOT #13 2023-08-07 14:37

MOT test number 799395335735

Result ✓ Passed

Next expiry date 2024-08-13

Advice Nearside Suspension arm pin or bush worn but not resulting in excessive movement inner rear (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement inner rear (5.3.4 (a) (i))

MOT #12 2022-08-04 10:12

MOT test number 778922248492

Result ✓ Passed

Advice Oil leak

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #11**

2022-08-02 10:04

MOT test number

613786337600

Result

✗ Failed

Fail Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

Fail Front Exhaust system insecure bracket broken (6.1.2 (a))

Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Inner Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Oil leak

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

MOT #10

2021-08-10 09:19

MOT test number

455710061537

Result

✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #9

2021-08-02 14:57

MOT test number

487733114503

Result

✗ Failed

Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

**MOT #8**

2020-08-06 09:35

MOT test number

364718225963

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Exhaust silencer heat shield lose in risk of coming off
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge only 3.0 mm of tread left (5.2.3 (e))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #7

2020-08-05 08:39

MOT test number

259128424645

Result

✗ Failed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge only 3.0 mm of tread left (5.2.3 (e))
- Advice** Oil leak, but not excessive Gearbox (8.4.1 (a) (i))
- Advice** Rear Exhaust silencer heat shield lose in risk of coming off
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Headlamp levelling device inoperative (4.1.5 (a))

MOT #6

2019-08-14 14:06

MOT test number

865270420468

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5**

2019-08-13 15:13

MOT test number

851595899296

Result**✗ Failed**

- Fail** Nearside Front Obligatory mirror insecure (3.3 (b) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Headlamp aim too high (4.1.2 (a))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4

2017-05-22 13:49

MOT test number

695533144008

Result**✓ Passed**

- Advice** Oil leak
- Advice** Front tyres wearing on edges

**MOT #3** 2017-05-19 13:22**MOT test number** 469730943995**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint drop link (2.4.G.2)**Advice** Front tyres wearing on edges**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint drop link (2.4.G.2)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Oil leak**MOT #2** 2016-02-12 15:27**MOT test number** 694025204323**Result** ✓ Passed**Advice** Engine/under covers fitted**MOT #1** 2015-02-17 16:10**MOT test number** 495768445055**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
13 August 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-25
Last registration	2023-08-07
Complete history	See info



Registration #1	2012-06-25	17 mi
Registration #2	2015-02-17	86.745 mi
Registration #3	2016-02-12	92.663 mi
Registration #4	2017-05-19	102.083 mi
Registration #5	2017-05-22	102.100 mi
Registration #6	2019-08-13	121.286 mi
Registration #7	2019-08-14	121.286 mi
Registration #8	2020-08-05	123.387 mi
Registration #9	2020-08-05	123.387 mi
Registration #10	2020-08-05	123.387 mi
Registration #11	2020-08-05	123.387 mi
Registration #12	2020-08-05	123.387 mi
Registration #13	2020-08-05	123.387 mi
Registration #14	2020-08-05	123.387 mi
Registration #15	2020-08-05	123.387 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBEJ3085743