





report date: 2024-03-29

## General information

Make	AUDI
Model	A3 TFSI SPORT
Colour	Grey
Year of manufacture	2010
Top speed	126 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	57.7 mpg
Consumption combined	46.3 mpg
CO2 emission	134 g/km
CO2 label	E



CarCheck.co.uk page 1/13



# Internet history


## Entry 1

Date 2021-05-26

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-05-30
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	33
Total items failed	8

MOT #14		2023-05-26 11:47
MOT test	number	190572845106
Result		✓ Passed
Next expi	ry date	2024-05-30
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge Edge worn (5.2.3 (e))		(e))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #13	2023-05-26 09:49	
MOT test number	200901638331	
Result	<b>×</b> Failed	
Fail Offside Front Windscreen wiper does not clear the windscreen effective	ly (3.4 (b) (ii))	
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge Edge worn (5.2.3 (e))		
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (	i))	
Advice Nearside Front Lower Suspension arm ball joint has slight play (5.3.4	4 (a) (i))	
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		

CarCheck.co.uk page 3/13



**AF10KXX** 

report date: 2024-03-29

Passed

**MOT #12** 2022-05-28 08:53

**MOT test number** 535486607657

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-05-18 14:54

**MOT test number** 198927359094

Advice Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))

Advice Front both tyres wearing inner edges slight and off side rear wearing inner edge lumpy tread

**Advice** Nearside Rear Coil spring corroded slight (5.3.1 (b) (i))

**Advice** Under trays

Result

MOT #10 2021-05-17 08:40

**MOT test number** 425331178851

**Result** X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Front both tyres wearing inner edges slight and off side rear wearing inner edge lumpy tread

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**Advice** Nearside Rear Coil spring corroded slight (5.3.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**Advice** Under trays

**Advice** Rear Brake pad(s) wearing thin all (1.1.13 (a) (ii))

**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Fail** Front Service brake excessively fluctuating both (1.2.1 (e))

CarCheck.co.uk page 4/13



AF10KXX

report date: 2024-03-29

MOT #9		2020-05-04 09:40
MOT test	number	349300351211
Result		✓ Passed
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Nearside Front Nail in tyre	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #8	2019-05-31 13:57
MOT test number	993157135450
Result	✓ Passed
MOT #7	2019-05-31 07:35
<b>MOT test number</b> 52181253079	
Result	<b>×</b> Failed
Fail Front Tyre tread depth below requirements of 1.6mm both 225/45/17 (5.2.3 (e))	

MOT #6		2018-05-03 13:34
MOT test	number	797932224005
Result		<b>✓</b> Passed
Advice	Under trays	
Advice	Rear brake pads slight wearing low	
Advice	Front both tyres wearing inner edges	
Advice	Front brake discs slight corrosion	

CarCheck.co.uk page 5/13



MOT #5 2017-05-08 14:22

**MOT test number** 605754252369

Result \( \sqrt{Passed} \)

**Advice** Under trays

MOT #4 2016-05-23 07:51

**MOT test number** 774036199815

**Result** ✓ Passed

MOT #3 2015-03-03 14:24

**MOT test number** 655982465073

**Result** 
✓ Passed

Advice Offside Outer Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Child seat fitted not allowing full inspection of adult belt

MOT #2 2014-02-14 13:45

**MOT test number** 486475144050

**Result** ✓ Passed

MOT #1 2013-02-18 09:46

**MOT test number** 608159543027

**Notice** O/s/f tyre worn on inner edge

**Notice** N/s/f tyre worn on inner edge

Advice Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	30 May 2024
Full MOT history	See MOT history

## Tax calculation

William .	40
Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



AF10KXX

report date: 2024-03-29

## Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when mistery		
For how long did the current and previous owner(s) have this AUDI? How many owners did Check it in the premium report and see all owner registrations. Download the full report		e?
***************************************		
*******		
***************************************		
	More info	
	More into	>
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		,
Current registration	NE UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	<b>&gt;</b>

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-01
Last registration	2023-05-26
Complete history	See info



Registration #1	2010-03-01	16 mi
Registration #2	2013-02-18	80.206 mi
Registration #3	2014-02-14	89.158 mi
Registration #4	2015-03-03	93.845 mi
Registration #5	2016-05-23	99.556 mi
Registration #6	2017-05-08	104.733 mi
Registration #7	2018-05-03	109.475 mi
Registration #8	2019-05-31	124.051 mi
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 mg

More info >

page 12/13 CarCheck.co.uk



# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1285 kg
Max. allowed weight	1855 kg

# Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number CAX473029