



BN09HTY

report date: 2024-03-28

General information

Make	MAZDA
Model	5 D SPORT NAV
Colour	Blue
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	11.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-14
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-07-15
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	33
Total items failed	17

MOT #16	2022-07-01 12:25
MOT test number	515572978052
Result	✓ Passed
Next expiry date	2023-07-15
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #15	2022-06-30 10:08
MOT test number	232135695295
Result	✗ Failed
Minor	Nearside Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #14**

2021-07-16 15:29

MOT test number

560805036566

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Anti-roll bar linkage ball joint has slight play Both (5.3.4 (a) (i))

MOT #13

2020-11-03 16:38

MOT test number

261515140737

Result

✓ Passed

Advice All suspension and floor pan corroded

MOT #12

2020-11-02 12:08

MOT test number

505742280526

Result

✗ Failed

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Front Registration plate inscription illegible (0.1 (b))

Advice All suspension and floor pan corroded

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Fail Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Offside Front Suspension component pin or bush excessively worn front bush to subframe (5.3.4 (a) (i))

Fail Rear Seat belt not functioning as intended rear center belt wrapped around seat (7.1.2 (c))

**MOT #11**

2019-04-27 09:07

MOT test number

558167224901

Result

✓ Passed

Advice Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Very dry in places need wax oil**MOT #10**

2018-05-03 10:59

MOT test number

420115713859

Result

✓ Passed

Advice Rear Tyre worn close to the legal limit both on inner edges (4.1.E.1)**Advice** Very dry and scaly in places advise to wax oil**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both lipped (3.5.1i)**MOT #9**

2017-05-02 16:22

MOT test number

835713620162

Result

✓ Passed

MOT #8

2017-05-02 08:46

MOT test number

763442088370

Result

✗ Failed

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Headlamp aim too low (1.8)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #7**

2016-05-10 12:24

MOT test number

180297958999

Result

✓ Passed

- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Tie bar/rod has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tie bar/rod has slight play in a ball joint (2.4.G.2)

MOT #6

2015-03-31 11:23

MOT test number

826750695006

Result

✓ Passed

- Notice** Tyres :: nsr tread low & distorting ,osr bald inner edge / tread distorting
- Notice** Rear brake pads close to limit
- Notice** Front wishbone bushes splitting/movement
- Notice** Knocking on rear drop links

MOT #5

2014-03-31 13:29

MOT test number

765680294029

Result

✓ Passed

- Notice** Slight binding to off side rear brake
- Notice** Slight binding to near side rear brake
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2014-03-28 16:37**MOT test number** 685467384058**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Rear discs rusted on edges.**Fail** Nearside Rear rear brake binding (3.7.B.1)**Notice** Both front tyres wearing on edges.**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Cut in o/s/r tyre outer side wall, but no cords showing.**Advice** Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-03-26 13:33**MOT test number** 188345583449**Result** ✓ Passed**MOT #2** 2012-09-25 10:00**MOT test number** 399489562207**Result** ✓ Passed**MOT #1** 2012-04-04 12:17**MOT test number** 337315492032**Result** ✓ Passed**Notice** Both rear tyres wearing on inner edges.**Notice** Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✕
Untaxed

Tax expired:
31 July 2022

✕
MOT

Expired:
15 July 2023

Tax status	Expired at 31 July 2022
Days left	638 days too late
MOT expiry date	15 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	BN09HTY
Plate since	2024-03-28
Current registration	BN09HTY
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-26
Last registration	2022-07-01
Complete history	See info



Registration #1	2009-03-26	25 mi
Registration #2	2012-04-04	34.903 mi
Registration #3	2012-09-25	42.309 mi
Registration #4	2013-03-26	48.900 mi
Registration #5	2014-03-28	60.802 mi
Registration #6	2014-03-31	60.808 mi
Registration #7	2015-03-31	74.959 mi
Registration #8	2016-05-10	84.720 mi
Registration #9	2017-05-02	97.441 mi
Registration #10	2018-05-02	111.217 mi
Registration #11	2019-05-02	125.000 mi
Registration #12	2020-05-02	138.783 mi
Registration #13	2021-05-02	152.566 mi
Registration #14	2022-05-02	166.349 mi
Registration #15	2023-05-02	180.132 mi
Registration #16	2024-05-02	193.915 mi
Registration #17	2025-05-02	207.698 mi
Registration #18	2026-05-02	221.481 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1535 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Engine number	RF 10246627