





General information

| Make | CITROEN |
|---------------------|----------------------|
| Model | C4 PURETECH PLATINUM |
| Colour | Grey |
| Year of manufacture | 2016 |
| Top speed | 108 mph |
| 0 - 60 mph | 12.3 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 81 BHP |
|-------------------------|---------------------|
| Max. torque | 118 Nm at 2.750 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 50.4 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 61.4 mpg |
| CO2 emission | 107 g/km |
| CO2 label | В |







Internet history

Entry 2

Date Pictures 2021-07-25

20

Listing price

View report



source: yesauto.com

| Entry 1 | |
|---------------|--------------------|
| Date | 2021-07-17 |
| Pictures | 12 |
| Listing price | <u>View report</u> |



source: cargurus.co.uk









MOT history

| MOT expiry date | 2025-04-16 |
|--------------------|------------|
| MOT pass rate | 86 % |
| MOT passed | 6 |
| Failed MOT tests | 1 |
| Total advice items | 9 |
| Total items failed | 1 |

| MOT #7 | 2024-04-04 07:58 |
|------------------|------------------|
| MOT test number | 995553876076 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-16 |

| MOT #6 | | 2023-04-04 13:48 |
|----------|---|------------------|
| MOT test | number | 368412362856 |
| Result | | 🗸 Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e)) | |
| Advice | Nearside Front tyre has slight damage to outer sidewall | |

| MOT #5 | 2023-04-04 11:42 |
|--|------------------|
| MOT test number | 911109447680 |
| Result | 🗙 Failed |
| Advice Nearside Front tyre has slight damage to outer sidewall | |
| Fail Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e)) | |





| MOT #4 | | 2022-04-07 11:15 |
|----------|--|------------------|
| MOT test | number | 416887490294 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre slightly damaged outer sidewall (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear tyre 3mm tread | |
| | | |

| МОТ #3 | 2021-04-07 10:05 |
|--|-----------------------|
| MOT test number | 921226433806 |
| Result | ✓ Passed |
| Advice Both rear tyres in tread slightly stepping | |
| Advice Front Lower Suspension arm pin or bush worn but not resulting in exercise (5.3.4 (a) (i)) | cessive movement both |

| MOT #2 | 2020-04-17 09:35 |
|-----------------|------------------|
| MOT test number | 794295310143 |
| Result | ✓ Passed |

| MOT #1 | 2019-03-21 10:26 |
|--|------------------|
| MOT test number | 121328151161 |
| Result | ✓ Passed |
| Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i)) | |



Tax & MOT check

| Tax due: 1 July 2024 | √ Taxed | Expires: 16 April 2025 | ✓ MOT Expires: 16 April 2025 | |
|--------------------------------|------------|----------------------------------|---------------------------------------|--|
| Tax status | | | Valid until 1 July | |
| Days left | | | 64 | |
| MOT expiry date | | | 16 April 2025 | |
| Full MOT history | | | See MOT history | |
| Tax calculation | | | | |
| Vehicle class | | 48 | | |

| Vehicle class | 48 |
|---|----------------|
| Band | В |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | | |
|----------|---------|-------|
| Date | | |
| Category | | Lamp |
| Туре | | |
| Damage 2 | | AMPL |
| Date | | · · · |
| Category | 1000000 | AMPL |
| Туре | | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| ********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plata since | |
| | |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2016-03-11 |
| Last registration | 2024-04-04 |
| Complete history | See info |



| Registration #1 | 2016-03-11 | 26 mi |
|------------------|------------|------------|
| Registration #2 | 2019-03-21 | 24.697 mi |
| Registration #3 | 2020-04-17 | 31.227 mi |
| Registration #4 | 2021-04-07 | 33.759 mi |
| Registration #5 | | 11.777 mi |
| Registration #6 | | 11.777 esi |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 10.200 est |

More info >





Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 83% |
| Children | 74% |
| Pedestrian | 33% |
| Safety systems | 40% |
| Overall rating | 67% |
| Video | see crash video |



| Dimensions & weight | |
|--|-------------------------------|
| Width | 1728 mm |
| Height | 1514 mm |
| Length | 3944 mm |
| Wheel base | 2451 mm |
| Kerb weight | 975 kg |
| Max. allowed weight | 1525 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 50 l |
| | 50 l Multi-Point Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Multi-Point Injection |
| Fuel tank capacity Fuel delivery Number of doors | Multi-Point Injection 5 |