



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY LX TDCI
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-27
Pictures	13
Listing price	View report



source: yesauto.com

**MOT history**

MOT #16	2022-03-25 16:03
MOT test number	506045335706
Result	✓ Passed
Next expiry date	2023-03-24
Advice	Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #15	2022-03-25 10:48
MOT test number	388485504278
Result	✗ Failed
Minor	Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Fail	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Front Brake pad(s) worn down to wear indicator both (1.1.13 (a) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))
Minor	Offside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Fail	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))
Advice	Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))

MOT #14	2021-01-15 15:31
MOT test number	693615118460
Result	✓ Passed
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2020-01-10 10:20**MOT test number** 832243221991**Result** ✓ Passed**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2019-01-04 13:11**MOT test number** 737812934404**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))**MOT #11** 2018-01-16 11:48**MOT test number** 107799413670**Result** ✓ Passed**MOT #10** 2018-01-16 11:48**MOT test number** 268961219662**Result** ✗ Failed**Pass with rectification** Nearside Inner Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #9** 2017-01-11 16:39**MOT test number** 832760461254**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2017-01-06 11:29**MOT test number** 550455019017**Result** ✗ Failed**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Trailing arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Rear Trailing arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**MOT #7** 2016-01-07 11:19**MOT test number** 289373817604**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2015-01-16 12:57**MOT test number** 127616115022**Result** ✓ Passed**MOT #5** 2012-09-28 14:53**MOT test number** 637782472253**Result** ✓ Passed

**MOT #4**

2012-09-27 15:01

MOT test number

625821672289

Result**✗ Failed****Fail** Nearside Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** O/s rear tyre low on inflation**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Item removed from front screen for MOT purpose see notes**MOT #3**

2011-10-17 09:00

MOT test number

347020691475

Result**✓ Passed****Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Power steering noisy no leaks at time of test**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2**

2010-11-01 16:06

MOT test number

471005500369

Result**✓ Passed****Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1**

2010-11-01 16:06

MOT test number

664315200337

Result**✗ Failed****Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Stop lamp not working (1.2.1b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-26
Last registration	2022-03-25
Complete history	See info



Registration #1	2007-09-26	29 mi
Registration #2	2010-11-01	39.001 mi
Registration #3	2011-10-17	56.693 mi
Registration #4	2012-09-27	75.683 mi
Registration #5	2012-09-28	75.683 mi
Registration #6	2015-01-16	94.714 mi
Registration #7	2016-01-07	102.830 mi
Registration #8	2017-01-06	110.438 mi
Registration #9	2017-01-11	110.523 mi
Registration #10	2019-05-29	151.377 mi
Registration #11	2019-05-29	151.377 mi
Registration #12	2019-05-29	151.377 mi
Registration #13	2019-05-29	151.377 mi
Registration #14	2019-05-29	151.377 mi
Registration #15	2019-05-29	151.377 mi
Registration #16	2019-05-29	151.377 mi
Registration #17	2019-05-29	151.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1793 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	7K35212
---------------	---------