



report date: 2024-03-29

General information

Make	CITROEN
Model	XSARA DESIRE 2 PICASSO
Colour	Blue
Year of manufacture	2005
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 3.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-09
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-02-25
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	25
Total items failed	19

MOT #23 2022-02-14 09:40

MOT test number 719641701097

Result ✓ Passed

Next expiry date 2023-02-25

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Power steering pipe/hose has slight seepage (2.1.5 (a))

MOT #22 2021-02-24 17:01

MOT test number 984384553748

Result ✓ Passed

MOT #21 2021-02-22 09:37

MOT test number 457890562277

Result ✗ Failed

Fail Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Advice Both front tyres worn on edges

**MOT #20** 2020-02-19 10:21**MOT test number** 951825097839**Result** ✓ Passed**Advice** The rear wiper blade is perishing**Minor** Windscreen wiper blade defective both wiper blades are perishing (3.4 (b) (i))**MOT #19** 2019-02-12 11:56**MOT test number** 187180649718**Result** ✓ Passed**Advice** Power steering pump has slight seepage (2.1.5 (a))**Advice** The nearside outer sill is slightly corroded**Advice** Exhaust has a minor leak of exhaust gases the rear silencer has split (6.1.2 (a))**Advice** Oil leak, but not excessive engine oil (8.4.1 (a) (i))**MOT #18** 2018-02-15 15:29**MOT test number** 871635632616**Result** ✓ Passed**Advice** Power steering pipes damp**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #17** 2018-02-14 10:19**MOT test number** 787838469183**Result** ✗ Failed**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Power steering pipes damp**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #16** 2017-02-13 12:31**MOT test number** 215579869884**Result** ✓ Passed**Advice** Power steering pipes damp close to excessive**MOT #15** 2016-02-25 09:34**MOT test number** 623235168226**Result** ✓ Passed**MOT #14** 2016-02-24 12:22**MOT test number** 739441853938**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #13** 2015-02-19 11:13**MOT test number** 647090955030**Result** ✓ Passed

**MOT #12** 2015-02-18 12:15**MOT test number** 706639345016**Result** ✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Fail Nearside Front Headlamp aim too low (1.8)

MOT #11 2014-02-21 13:32**MOT test number** 289692554044**Result** ✓ Passed**MOT #10** 2014-02-21 13:32**MOT test number** 418022954009**Result** ✗ Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

MOT #9 2013-02-26 16:39**MOT test number** 747227653063**Result** ✓ Passed

Advice Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Offside rear tyre uneven wear

**MOT #8** 2013-02-25 14:02**MOT test number** 638086353008**Result** ✗ Failed**Notice** Offside rear tyre uneven wear**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Nearside Steering rack gaiter split (2.2.D.2d)**MOT #7** 2011-12-01 12:01**MOT test number** 467375531335**Result** ✓ Passed**Notice** Air bag light on**MOT #6** 2011-12-01 12:01**MOT test number** 639455031354**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Notice** Air bag light on**Pass with rectification** Nearside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**MOT #5** 2010-12-06 12:30**MOT test number** 492690840350**Result** ✓ Passed

**MOT #4** 2010-12-06 12:30**MOT test number** 581680740395**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2009-12-04 10:01**MOT test number** 901428439361**Result** ✓ Passed**Notice** Both rear tyre sidewalls cracking(perished)**MOT #2** 2009-12-04 10:01**MOT test number** 314438139383**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Notice** Both rear tyre sidewalls cracking(perished)**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #1** 2008-08-27 10:06**MOT test number** 520240248218**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✕
Untaxed

Tax expired:
10 October 2022

✕
MOT

Expired:
25 February 2023

Tax status	Expired at 10 October 2022
Days left	568 days too late
MOT expiry date	25 February 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	BF55RYM
Plate since	2019-03-29
Current registration	BF55RYM
Plate since	2019-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-15
Last registration	2022-02-14
Complete history	See info



Registration #1	2005-09-15	25 mi
Registration #2	2008-08-27	34.172 mi
Registration #3	2009-12-04	41.778 mi
Registration #4	2010-12-06	50.805 mi
Registration #5	2011-12-01	61.867 mi
Registration #6	2013-02-25	66.226 mi
Registration #7	2013-02-26	66.226 mi
Registration #8	2014-02-21	72.176 mi
Registration #9	2015-02-18	78.427 mi
Registration #10	2015-02-19	78.437 mi
Registration #11	2016-02-24	84.126 mi
Registration #12	2016-02-25	85.000 mi
Registration #13	2016-02-26	85.000 mi
Registration #14	2016-02-27	85.000 mi
Registration #15	2016-02-28	85.000 mi
Registration #16	2016-03-01	85.000 mi
Registration #17	2016-03-02	85.000 mi
Registration #18	2016-03-03	85.000 mi
Registration #19	2016-03-04	85.000 mi
Registration #20	2016-03-05	85.000 mi
Registration #21	2016-03-06	85.000 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1240 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7C2721483