




report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D DRIVE SE
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2

Date	2021-07-14
Pictures	57
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-12
Pictures	11
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2023-07-06
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	36
Total items failed	3

MOT #15	2022-07-01 11:25
MOT test number	707903313388
Result	✓ Passed
Next expiry date	2023-07-06

MOT #14	2022-07-01 11:25
MOT test number	773375738534
Result	✗ Failed
Pass with rectification	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #13	2021-07-07 06:10
MOT test number	889598651946
Result	✓ Passed

**MOT #12**

2021-06-22 12:00

MOT test number

687380753999

Result**✗ Failed**

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))

MAJOR Rear Service brake excessively fluctuating (1.2.1 (e))

MAJOR Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

MOT #11

2020-03-23 10:40

MOT test number

353238738233

Result**✓ Passed**

Advice Suspension arm pin or bush worn but not resulting in excessive movement o/s/f lower arm rear
bush (5.3.4 (a) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear disc (1.1.14 (a) (ii))

MOT #10

2020-03-23 10:21

MOT test number

371437805329

Result**✗ Failed**

Advice Brake disc worn, pitted or scored, but not seriously weakened both rear disc (1.1.14 (a) (ii))

MAJOR Suspension arm pin or bush excessively worn n/s/f lower wishbone rear bush (5.3.4 (a) (i))

MAJOR Outline marker lamp not working both front (4.2.1 (a) (ii))

Advice Suspension arm pin or bush worn but not resulting in excessive movement o/s/f lower arm rear
bush (5.3.4 (a) (i))

**MOT #9**

2019-03-29 11:04

MOT test number

792729709567

Result

✓ Passed

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both O/Side & N/Side (1.1.14 (a) (ii))

Advice Rear Service brake fluctuating, but not excessively Both O/Side & N/Side (1.2.1 (e))

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened Both O/Side & N/Side (1.1.14 (a) (ii))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both O/Side & N/Side rear control arm bushes (5.3.4 (a) (i))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2019-03-22 11:18

MOT test number

413550696919

Result

✗ Failed

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Front Lower Coil spring fractured or broken (5.3.1 (b) (i))

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened Both O/Side & N/Side (1.1.14 (a) (ii))

Advice Rear Service brake fluctuating, but not excessively Both O/Side & N/Side (1.2.1 (e))

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened Both O/Side & N/Side (1.1.14 (a) (ii))

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both O/Side & N/Side rear control arm bushes (5.3.4 (a) (i))

MOT #7

2018-03-29 15:13

MOT test number

644743236102

Result

✓ Passed

Advice Rear brake pads wearing thin

Advice Nearside front suspension arm rear bush perishing

Advice Rear brake discs corroded on inner face

Advice Both rear tyre misshaped on inner edge

**MOT #6** 2017-03-31 09:47**MOT test number** 370562992197**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**MOT #5** 2016-03-24 11:58**MOT test number** 856405128351**Result** ✓ Passed**MOT #4** 2015-03-31 15:19**MOT test number** 247980995063**Result** ✓ Passed**MOT #3** 2015-03-31 12:21**MOT test number** 667330495078**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2014-03-01 15:44
MOT test number	197840464465
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-03-28 10:32
MOT test number	547597183078
Result	✓ Passed
Notice	Both rear tyres tread uneven
Notice	Offside number plate lamp dim



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

X

MOT

Expired:
6 July 2023

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	6 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-31
Last registration	2022-07-01
Complete history	See info



Registration #1	2010-03-31	25 mi
Registration #2	2013-03-28	29.549 mi
Registration #3	2014-03-01	39.029 mi
Registration #4	2015-03-31	56.504 mi
Registration #5	2015-03-31	56.504 mi
Registration #6	2016-03-24	69.207 mi
Registration #7	2017-03-31	81.804 mi
Registration #8	2018-03-29	97.299 mi
Registration #9	2019-03-22	109.294 mi
Registration #10	2019-03-22	109.294 mi
Registration #11	2019-03-22	109.294 mi
Registration #12	2019-03-22	109.294 mi
Registration #13	2019-03-22	109.294 mi
Registration #14	2019-03-22	109.294 mi
Registration #15	2019-03-22	109.294 mi
Registration #16	2019-03-22	109.294 mi
Registration #17	2019-03-22	109.294 mi
Registration #18	2019-03-22	109.294 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1405 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	910901