



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 T2 R-DESIGN
Colour	Black
Year of manufacture	2016
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	220 Nm at 1.100 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D





Internet history

Entry 2


Date	2023-03-06
Pictures	19
Listing price	View report



source: autotrader.co.uk

Entry 1

Date	2021-01-22
Pictures	39
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-03-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	0

MOT #8	2024-03-16 11:04
MOT test number	912883527825
Result	✓ Passed
Next expiry date	2025-03-15

MOT #7	2024-03-15 08:43
MOT test number	810176468726
Result	✗ Failed
DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm uneven centre of tread (5.2.3 (e))	

MOT #6	2022-12-10 11:18
MOT test number	330633260165
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm on inner edge and is mishapen (5.2.3 (e))	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.5mm on inner edge and is mishapen (5.2.3 (e))	
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Nearside Front Inner wheel arch liner is damaged	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

**MOT #5** 2021-12-15 11:00**MOT test number** 416399304773**Result** ✓ Passed**Advice** Front bumper damaged broken**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre slightly damaged stepped inner edge (5.2.3 (d) (ii))**MOT #4** 2021-12-14 16:23**MOT test number** 621494708449**Result** ✗ Failed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Tyre slightly damaged stepped inner edge (5.2.3 (d) (ii))**Advice** Front bumper damaged broken**MAJOR** Reversing lamp inoperative (4.6.1 (a))**MOT #3** 2020-12-15 15:56**MOT test number** 360292963039**Result** ✓ Passed**MOT #2** 2020-06-26 09:19**MOT test number** 676802180824**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #1** 2019-07-05 09:21**MOT test number** 517078401311**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-07-21
Last registration	2024-03-16
Complete history	See info



Registration #1	2016-07-21	7 mi
Registration #2	2019-07-05	21.366 mi
Registration #3	2020-06-26	26.633 mi
Registration #4	2020-12-15	27.757 mi
Registration #5	2021-06-20	28.277 mi
Registration #6	2021-12-14	35.318 mi
Registration #7	2022-06-20	35.277 mi
Registration #8	2022-06-20	35.277 mi
Registration #9	2022-06-20	35.277 mi
Registration #10	2022-06-20	35.277 mi
Registration #11	2022-06-20	35.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1417 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1682982