



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2010
Top speed	147 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.5 mpg
Consumption extra urban	48.7 mpg
Consumption combined	36.2 mpg
CO2 emission	188 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-07-02
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	5
Total items failed	5

MOT #14	2023-10-09 13:30
MOT test number	830298359883
Result	✓ Passed
Next expiry date	2024-10-08
Minor	Offside Front Outer Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #13	2022-09-16 09:09
MOT test number	774633731894
Result	✓ Passed

MOT #12	2021-10-02 09:54
MOT test number	476646135893
Result	✓ Passed
Advice	Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))

**MOT #11** 2021-10-01 14:36**MOT test number** 939278031943**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (1.1.14 (a) (ii))**Fail** Coil spring fractured or broken Both rear (5.3.1 (b) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2021-03-02 15:51**MOT test number** 611922615807**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Rear Brake pipe corroded, covered in grease or other material BOTH SIDES ACROSS AXLE (1.1.11 (c))**MOT #9** 2020-03-05 12:36**MOT test number** 867943202656**Result** ✓ Passed**MOT #8** 2018-11-01 11:45**MOT test number** 414330636679**Result** ✓ Passed**MOT #7** 2017-07-13 12:09**MOT test number** 230776905616**Result** ✓ Passed

**MOT #6** 2017-07-10 10:16**MOT test number** 341865747694**Result** ✗ Failed**Fail** Offside Front Front suspension ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #5** 2016-07-07 08:18**MOT test number** 864524288362**Result** ✓ Passed**MOT #4** 2015-07-03 11:21**MOT test number** 559664385155**Result** ✓ Passed**MOT #3** 2014-06-20 13:02**MOT test number** 307191974137**Result** ✓ Passed**MOT #2** 2013-07-09 11:11**MOT test number** 715840493184**Result** ✓ Passed**MOT #1** 2012-12-18 12:16**MOT test number** 318733352373**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 September 2023

✓

MOT

Expires:
8 October 2024

Tax status	Expired at 1 September
Days left	241 days too late
MOT expiry date	8 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-02-08
Last registration	2023-10-09
Complete history	See info



Registration #1	2010-02-08	18 mi
Registration #2	2012-12-18	44.898 mi
Registration #3	2013-07-09	47.331 mi
Registration #4	2014-06-20	51.367 mi
Registration #5	2015-07-03	58.009 mi
Registration #6	2016-07-07	62.950 mi
Registration #7	2017-07-10	69.193 mi
Registration #8	2017-07-13	69.193 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1390 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431327318