



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | VOLVO |
| Model | C70 T5 SE |
| Colour | Blue |
| Year of manufacture | 2007 |
| Top speed | 150 mph |
| 0 - 60 mph | 7.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 220 BHP |
| Max. torque | 320 Nm at 4.800 rpm |
| Engine capacity | 2.521 cc |
| Cylinders | 5 |
| Fuel type | Petrol |
| Consumption city | 21.6 mpg |
| Consumption extra urban | 42.2 mpg |
| Consumption combined | 31.0 mpg |
| CO2 emission | 217 g/km |
| CO2 label | K |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-20 |
| Pictures | 32 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-10-06 |
| MOT pass rate | 68 % |
| MOT passed | 15 |
| Failed MOT tests | 7 |
| Total advice items | 36 |
| Total items failed | 15 |

MOT #22 2023-10-07 13:30

MOT test number 546333212698

Result ✓ Passed

Next expiry date 2024-10-06

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Coil spring corroded Both sides (5.3.1 (b) (i))
- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #21 2022-10-06 14:11

MOT test number 265229360148

Result ✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #20**

2022-09-16 13:15

MOT test number

771678476234

Result

✗ Failed

Advice

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Fail

Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))

Fail

Nearside Rear Brake pad(s) contaminated (1.1.13 (b))

Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))

Fail

Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Fail

Front passenger door cannot be opened from inside the vehicle (6.2.3 (a))

Fail

Nearside Rear Brake disc contaminated (1.1.14 (b))

MOT #19

2021-09-13 10:55

MOT test number

697853794091

Result

✓ Passed

Advice

Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #18

2021-04-19 09:37

MOT test number

807281606156

Result

✓ Passed

Advice

Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Exhaust deteriorated

Advice

Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor

Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Rear Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

**MOT #17** 2020-03-12 12:45**MOT test number** 240409400458**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2020-03-04 16:40**MOT test number** 713415868340**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #15** 2019-03-20 14:22**MOT test number** 235162277713**Result** ✓ Passed**MOT #14** 2019-03-14 13:00**MOT test number** 109915295544**Result** ✗ Failed**Fail** Offside Rear Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #13** 2018-03-10 13:56**MOT test number** 129240242835**Result** ✓ Passed**Advice** General underside corrosion

**MOT #12** 2017-03-17 13:50**MOT test number** 161943697282**Result** ✓ Passed**MOT #11** 2016-04-28 17:20**MOT test number** 676860075472**Result** ✓ Passed**MOT #10** 2016-04-28 09:33**MOT test number** 137072661483**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #9** 2015-05-01 13:50**MOT test number** 279761425153**Result** ✓ Passed**MOT #8** 2015-04-30 10:24**MOT test number** 859470525160**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Tyre has ply or cords exposed (4.1.D.1b)**MOT #7** 2014-05-08 10:15**MOT test number** 298638924409**Result** ✓ Passed**MOT #6** 2013-05-10 10:44**MOT test number** 698000233168**Result** ✓ Passed

**MOT #5** 2012-05-14 17:02**MOT test number** 937585332144**Result** ✓ Passed

- Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Screw in offside front tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-05-14 11:08**MOT test number** 119015132186**Result** ✗ Failed

- Fail** Horn not working (1.6.2a)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Notice** Screw in offside front tyre
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2011-05-19 18:09**MOT test number** 957859031173**Result** ✓ Passed

- Notice** All discs surface rust



| | |
|-----------------|--|
| MOT #2 | 2010-03-10 16:16 |
| MOT test number | 633889160053 |
| Result | ✓ Passed |
| Advice | Nearside Front brake disc slightly pitted (3.5.1h) |

| | |
|-----------------|--|
| MOT #1 | 2010-03-09 11:29 |
| MOT test number | 591488060098 |
| Result | ✗ Failed |
| Advice | Nearside Front brake disc slightly pitted (3.5.1h) |
| Fail | Nearside Rear Brake lining(s) insecure (3.5.1g) |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 October 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 6 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-28 |
| Current registration | ***** |
| Plate since | 2019-06-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2007-03-27 |
| Last registration | 2023-10-07 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-03-27 | 13 mi |
| Registration #2 | 2010-03-09 | 22.833 mi |
| Registration #3 | 2010-03-10 | 22.833 mi |
| Registration #4 | 2011-05-19 | 24.684 mi |
| Registration #5 | 2012-05-14 | 28.687 mi |
| Registration #6 | 2012-05-14 | 28.687 mi |
| Registration #7 | 2013-05-10 | 31.661 mi |
| Registration #8 | 2014-05-08 | 34.615 mi |
| Registration #9 | 2015-04-30 | 38.243 mi |
| Registration #10 | 2015-05-01 | 38.243 mi |
| Registration #11 | 2016-04-28 | 41.534 mi |
| Registration #12 | 2016-04-28 | 41.534 mi |
| Registration #13 | 2016-05-01 | 41.534 mi |
| Registration #14 | 2016-05-01 | 41.534 mi |
| Registration #15 | 2016-05-01 | 41.534 mi |
| Registration #16 | 2016-05-01 | 41.534 mi |
| Registration #17 | 2016-05-01 | 41.534 mi |
| Registration #18 | 2016-05-01 | 41.534 mi |
| Registration #19 | 2016-05-01 | 41.534 mi |
| Registration #20 | 2016-05-01 | 41.534 mi |
| Registration #21 | 2016-05-01 | 41.534 mi |
| Registration #22 | 2016-05-01 | 41.534 mi |
| Registration #23 | 2016-05-01 | 41.534 mi |
| Registration #24 | 2016-05-01 | 41.534 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1820 mm |
| Height | 1400 mm |
| Length | 4582 mm |
| Wheel base | 2640 mm |
| Max. allowed weight | 2090 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 62 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of axles | 2 |
| Engine number | 3992248 |