



RENAULT

MV06NJY

report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL29DCI 100 SWB P/V
Colour	White
Year of manufacture	-
Top speed	97 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	200 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.2 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	35
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #18</b>	2021-01-07 12:09
<b>MOT test number</b>	845517262750
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-01-09
<b>Advice</b>	Nearside Front Play in steering rack inner joint(s)
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #17</b>	2020-01-10 09:00
<b>MOT test number</b>	571949459421
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Position lamp slightly affected by the operation of another lamp both n/s and o/s (4.2.3 (c))
<b>Advice</b>	Bonnet catch broken
<b>Advice</b>	Coolant leak
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

<b>MOT #16</b>	2019-01-31 15:11
<b>MOT test number</b>	738164039065
<b>Result</b>	✓ Passed

<b>MOT #15</b>	2018-02-09 09:08
<b>MOT test number</b>	831599775572
<b>Result</b>	✓ Passed

<b>MOT #14</b>	2017-01-11 15:34
<b>MOT test number</b>	465052242521
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Rear position lamp(s) slightly discoloured (1.1.A.3e)

**MOT #13** 2016-02-11 16:43**MOT test number** 880071707963**Result** ✓ Passed

**Advice** Parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.D.3b)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2015-05-02 12:54**MOT test number** 158542325111**Result** ✓ Passed

**Notice** Wipers

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #11** 2015-05-02 10:22**MOT test number** 607882725195**Result** ✗ Failed

**Fail** Offside Rear coil spring broken (2.4.C.1a)

**Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)

**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**Notice** Wipers

**Fail** Rear Registration plate lamp not working (1.1.C.1d)

**MOT #10** 2014-05-10 11:04**MOT test number** 608310234140**Result** ✓ Passed

**MOT #9** 2013-05-24 12:12**MOT test number** 905984443183**Result** ✓ Passed**MOT #8** 2013-05-17 12:54**MOT test number** 188187533101**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #7** 2012-05-23 15:56**MOT test number** 359254842105**Result** ✓ Passed**MOT #6** 2012-03-14 08:01**MOT test number** 405024772034**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Wear on discs and pads**Notice** Stiffness in both front suspension top mounts

**MOT #5** 2012-03-07 17:07**MOT test number** 557767962020**Result** ✗ Failed**Fail** Offside Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Wear on discs and pads**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Notice** Stiffness in both front suspension top mounts**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Nail in offside rear tyre**Fail** Offside Stop lamp not working (1.2.1b)**MOT #4** 2010-12-11 10:59**MOT test number** 460365940377**Result** ✓ Passed**MOT #3** 2010-12-10 17:48**MOT test number** 502144340304**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front registration plate deteriorated (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2	2009-12-08 16:03
MOT test number	472602549357
Result	✓ Passed
MOT #1	2009-01-06 10:23
MOT test number	200106309094
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-18
Last registration	2021-01-07
Complete history	<a href="#">See info</a>



Registration #1	2006-03-18	16 mi
Registration #2	2009-01-06	38.256 mi
Registration #3	2009-12-08	51.922 mi
Registration #4	2010-12-10	68.194 mi
Registration #5	2010-12-11	68.194 mi
Registration #6	2012-03-07	83.416 mi
Registration #7	2012-03-14	83.416 mi
Registration #8	2012-05-23	83.213 mi
Registration #9	2013-05-17	90.699 mi
Registration #10	2013-05-24	90.699 mi
Registration #11	2013-05-24	90.699 mi
Registration #12	2013-05-24	90.699 mi
Registration #13	2013-05-24	90.699 mi
Registration #14	2013-05-24	90.699 mi
Registration #15	2013-05-24	90.699 mi
Registration #16	2013-05-24	90.699 mi
Registration #17	2013-05-24	90.699 mi
Registration #18	2013-05-24	90.699 mi
Registration #19	2013-05-24	90.699 mi
Registration #20	2013-05-24	90.699 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Length	4782 mm
Kerb weight	1684 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	C642545