





#### General information

Make	MERCEDES
Model	CLK CLK200K SPORT
Colour	Black
Year of manufacture	2007
Top speed	144 mph
Gearbox	6 speed automatic

# Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K







# Internet history

Entry 1

Date

Pictures

2021-11-18

32

Listing price

View report









source: cargurus.co.uk



# MOT history

MOT expiry date	2025-01-30
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	12
Total items failed	12

MOT #18		2024-01-31 16:48
MOT test	number	750665810659
Result		✓ Passed
Next expi	ry date	2025-01-30
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (	z))
Advice	Rear light corrosion on undercarriage	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c	))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #17	2023-01-20 17:28
MOT test number	192372278010
Result	✓ Passed





MOT #1	L6	2023-01-18 11:53
MOT te	st number	791173299730
Result		🗙 Failed
Fail	Offside Front Lower Suspension arm pin or bush excessively worn rear (5.3.4 (a) (i)	)
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	ail Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Fail	Front Brake disc in such a condition that it is seriously weakened $(1.1.14$ (a) (ii))	
<b>Fail</b> (ii))	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingres	ss of dirt (5.3.4 (b)
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	

MOT #15	2022-01-31 14:38
MOT test number	716199994106
Result	✓ Passed
MOT #14	2021-06-24 09:22
MOT test number	926709776281
Result	✓ Passed
MOT #13	2020-07-31 07:00
MOT test number	110739898468
Result	✓ Passed





MOT #12	2020-07-29 09:50
MOT test number	605927370931
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Track rod end ball joint has excessive play both (2.1.3 (b) (i))	

MOT #11	2019-04-09 15:46
MOT test number	915212971672
Result	✓ Passed
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2018-04-11 09:29
MOT test number	844440171021
Result	✓ Passed

MO	T #9		2017-04-19 09:00
MO	T test	number	214994907892
Res	ult		✓ Passed
A	dvice	Oil leak	
A	dvice	Front suspension has slight play in a lower suspension ball joint both (2.5.B.1a)	
A	dvice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
A	dvice	Slight cuts to nearside front tyre	

MOT #8	2016-04-20 09:17
MOT test number	125650451809
Result	✓ Passed





MOT #7	2015-04-18 09:42
MOT test number	625678905138
Result	✓ Passed
MOT #6	2015-04-14 11:25
MOT test number	328194005121
Result	× Failed
Fail   Nearside Front Road wheel distorted (4.2.A.1a)	
MOT #5	2013-12-19 11:36
MOT test number	108763853384
Result	✓ Passed
MOT #4	2012-12-17 10:18
MOT test number	355202752375
Result	✓ Passed
MOT #3	2011-12-09 11:25
MOT test number	489803441386
Result	✓ Passed
MOT #2	2011-12-09 11:25
MOT test number	795463141356
Result	× Failed
Pass with rectification   Offside Headlamp aim too high (1.8)	
MOT #1	2010-11-24 15:19

MOT #1	2010-11-24 15:19
MOT test number	481308720382
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 30 January 2025
Tax status	Valid until 1 February
Days left	277
MOT expiry date	30 January 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	APMPE
Туре	
Damage 2	AMPLE
	F St I
Date	AF 1
Category	ant
Туре	

#### Extra MERCEDES salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

********	
***********	
********	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-12-17
Last registration	2024-01-31
Complete history	See info



Registration #1	2007-12-17	24 mi
Registration #2	2010-11-24	35.747 mi
Registration #3	2011-12-09	38.970 mi
Registration #4	2012-12-17	40.913 mi
Registration #5	2013-12-19	47.690 mi
Registration #6	2015-04-14	50.802 mi
Registration #7	2015-04-18	50.804 mi
Registration #8	2016-04-20	66.354 mi
Registration #9	2017-04-19	82.074 mi
Registration #10	2018-04-11	95.307 mi
Registration #10 Registration #11	2018-04-11	95.307 mi
-	2018-04-11	95.307 mi
Registration #11	2018-04-11	95.307 mi
Registration #11 Registration #12	2018-04-11	95.307 mi
Registration #11 Registration #12 Registration #13	2018-04-11	95.307 mi
Registration #11 Registration #12 Registration #13 Registration #14	2018-04-11	95.307 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15	2018-04-11	95.307 mi
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	2018-04-11	95.307 mi





# Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg
Max. allowed weight	2145 kg

# Additional information

Fuel tank capacity	62
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195530868737