



report date: 2024-03-28

General information

Make	AUDI
Model	TT TDI S LINE
Colour	Grey
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	320 Nm at 2.100 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	65.7 mpg
Consumption combined	51.4 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-28
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-01-30
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	37
Total items failed	11

MOT #19	2024-01-26 13:42
MOT test number	400393845572
Result	✓ Passed
Next expiry date	2025-01-30
Advice	Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #18	2023-01-31 14:56
MOT test number	622514487063
Result	✓ Passed

MOT #17	2022-03-05 16:12
MOT test number	148105319572
Result	✓ Passed

MOT #16	2021-05-15 13:18
MOT test number	129999260764
Result	✓ Passed

**MOT #15** 2021-05-14 15:43**MOT test number** 748990528730**Result** ✗ Failed**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #14** 2020-08-08 11:30**MOT test number** 215650367753**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Front Upper Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Lower Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #13** 2019-06-29 08:15**MOT test number** 912967867658**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides wear (1.1.14 (a) (ii))**Advice** Front Tyre worn close to legal limit/worn on edge Both sides 2mm and also wear on inner tread (5.2.3 (e))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides wear (1.1.14 (a) (ii))**MOT #12** 2018-06-07 12:19**MOT test number** 230460279793**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

**MOT #11** 2018-06-07 10:11**MOT test number** 403604449424**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**MOT #10** 2017-07-03 08:10**MOT test number** 866065007088**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #9** 2016-07-06 11:53**MOT test number** 819064705545**Result** ✓ Passed**MOT #8** 2015-04-08 17:13**MOT test number** 197978395093**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Tyre monitoring lamp flashing on dash**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2015-04-08 12:56**MOT test number** 687358795082**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Tyre monitoring lamp flashing on dash**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-04-09 09:15**MOT test number** 449189094042**Result** ✓ Passed**MOT #5** 2013-10-22 14:04**MOT test number** 707095993276**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2013-10-21 15:12**MOT test number** 438644793280**Result** ✗ Failed**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Service lamp on**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s front wiper smearing windscreen**Notice** Water level low**MOT #3** 2012-10-16 10:03**MOT test number** 818640192269**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-10-22 09:50**MOT test number** 478115891213**Result** ✓ Passed



MOT #1	2011-10-21 12:17
MOT test number	376964691469
Result	✗ Failed
Fail	Rear registration plate character(s) incorrectly spaced (6.3.4a)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Front registration plate character(s) incorrectly spaced (6.3.4a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	KX58OZF
Plate since	2019-09-28
Current registration	KX58OZF
Plate since	2019-09-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-12-22
Last registration	2024-01-26
Complete history	See info



Registration #1	2008-12-22	26 mi
Registration #2	2011-10-21	44.592 mi
Registration #3	2011-10-22	44.593 mi
Registration #4	2012-10-16	49.246 mi
Registration #5	2013-10-21	52.085 mi
Registration #6	2013-10-22	52.084 mi
Registration #7	2014-04-09	52.881 mi
Registration #8	2015-04-08	67.834 mi
Registration #9	2015-04-08	67.834 mi
Registration #10	2016-07-06	81.205 mi
Registration #11	2017-07-03	96.189 mi
Registration #12	2018-01-22	111.207 mi
Registration #13	2018-01-22	111.207 mi
Registration #14	2018-01-22	111.207 mi
Registration #15	2018-01-22	111.207 mi
Registration #16	2018-01-22	111.207 mi
Registration #17	2018-01-22	111.207 mi
Registration #18	2018-01-22	111.207 mi
Registration #19	2018-01-22	111.207 mi
Registration #20	2018-01-22	111.207 mi
Registration #21	2018-01-22	111.207 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1460 kg
Max. allowed weight	2010 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CAG 131084