



report date: 2024-03-29

General information

Make	VOLVO
Model	V40 D2 CROSS COUNTRY LUX NAV
Colour	Bronze
Year of manufacture	2015
Top speed	115 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1	
Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-06-06
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	4
Total items failed	2

MOT #9	2023-06-07 16:26
MOT test number	530333776298
Result	✓ Passed
Next expiry date	2024-06-06
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #8	2022-02-14 10:26
MOT test number	192102607396
Result	✓ Passed
Advice	Nearside Front Track rod end ball joint has slight play inner rack arm ball joint (2.1.3 (b) (i))

MOT #7	2021-02-09 09:05
MOT test number	255702612585
Result	✓ Passed
Advice	Nearside Rear Nail in tyre

MOT #6	2020-07-21 09:50
MOT test number	631379875698
Result	✓ Passed

**MOT #5** 2020-07-21 08:14**MOT test number** 776938760832**Result** ✗ Failed**Fail** Brake pad(s) less than 1.5 mm thick front and rear (1.1.13 (a) (ii))**MOT #4** 2019-07-15 13:57**MOT test number** 200403382161**Result** ✓ Passed**MOT #3** 2019-07-15 09:35**MOT test number** 557786250232**Result** ✗ Failed**Advice** Rear Tyre worn close to legal limit/worn on edge nearside and offside (5.2.3 (e))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2018-07-30 14:16**MOT test number** 982483451138**Result** ✓ Passed**MOT #1** 2017-10-10 14:37**MOT test number** 370439708960**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
6 June 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	6 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-03-06
Last registration	2023-06-07
Complete history	<a href="#">See info</a>



Registration #1	2015-03-06	13 mi
Registration #2	2017-10-10	54.869 mi
Registration #3	2018-07-30	57.692 mi
Registration #4	2019-07-15	74.397 mi
Registration #5	2019-07-15	74.397 mi
Registration #6	2020-07-21	85.412 mi
Registration #7	2020-07-21	85.412 mi
Registration #8	2020-07-21	85.412 mi
Registration #9	2020-07-21	85.412 mi
Registration #10	2020-07-21	85.412 mi
Registration #11	2020-07-21	85.412 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2041 mm
Height	1458 mm
Length	4370 mm
Wheel base	2646 mm
Kerb weight	1429 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4153612