



RENAULT



LS600PC

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 2

Date	2023-12-12
Pictures	8



source: g3remarketing.co.uk

Entry 1

Date	2021-07-31
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-02
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	28
Total items failed	9

MOT #17	2023-08-03 15:39
MOT test number	206382745311
Result	✓ Passed
Next expiry date	2024-08-02
Advice	Offside Front door check strap faulty
Advice	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #16	2023-08-01 08:24
MOT test number	602875989433
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
DANGEROUS	Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
Advice	Offside Front door check strap faulty
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
DANGEROUS	Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
MAJOR	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #15	2022-07-28 16:12
MOT test number	896063941945
Result	✓ Passed

MOT #14	2021-07-31 11:41
MOT test number	549545948050
Result	✓ Passed

Advice	UNDERTRAYS FITTED
---------------	-------------------

**MOT #13** 2021-07-31 11:41**MOT test number** 315475110104**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** UNDERTRAYS FITTED**MOT #12** 2020-10-10 11:26**MOT test number** 620342502156**Result** ✓ Passed**MOT #11** 2020-10-03 08:53**MOT test number** 918223761083**Result** ✗ Failed**DANGEROUS** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #10** 2019-04-15 12:39**MOT test number** 324094654311**Result** ✓ Passed**MOT #9** 2018-05-21 08:31**MOT test number** 459481032262**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2017-06-17 06:38**MOT test number** 340417352016**Result** ✓ Passed**MOT #7** 2017-06-15 13:55**MOT test number** 921912597629**Result** ✗ Failed**Fail** Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front tyre bold on inner edge and inner sidewall damaged**Fail** Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**Advice** Rear brake discs poor condition**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Nearside Front tyre bold on inner edge and perished**Advice** Front brake discs poor condition**MOT #6** 2016-07-15 11:36**MOT test number** 495028365769**Result** ✓ Passed**Advice** Both front tyres low on inner edges**Advice** Rear brake pads low 3/4000 miles max

**MOT #5** 2016-07-15 10:40**MOT test number** 682221372599**Result** ✗ Failed**Advice** Both front tyres low on inner edges**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear brake pads low 3/4000 miles max**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-07-09 12:07**MOT test number** 579900395166**Result** ✓ Passed**MOT #3** 2015-07-09 12:07**MOT test number** 989480795180**Result** ✗ Failed**Pass with rectification** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #2** 2014-07-21 13:50**MOT test number** 145602204200**Result** ✓ Passed**MOT #1** 2013-09-17 13:05**MOT test number** 937740963282**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
2 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	2 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-29
Last registration	2023-08-03
Complete history	See info



Registration #1	2010-09-29	17 mi
Registration #2	2013-09-17	31.531 mi
Registration #3	2014-07-21	40.661 mi
Registration #4	2015-07-09	47.059 mi
Registration #5	2016-07-15	57.435 mi
Registration #6	2016-07-15	57.435 mi
Registration #7	2017-06-15	62.015 mi
Registration #8	2017-06-17	62.087 mi
Registration #9	2018-05-21	65.654 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi
Registration #17	2019-05-29	75.277 mi
Registration #18	2019-05-29	75.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D051208
---------------	---------