



report date: 2024-03-28

General information

Make	VOLVO
Model	V50 D2 R-DESIGN
Colour	Red
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2022-05-23
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	4

MOT #13 2023-05-10 14:04

MOT test number 379028115839

Result ✓ Passed

Next expiry date 2024-05-19

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #12 2023-05-09 11:53

MOT test number 433751889176

Result ✗ Failed

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Fail Offside Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #11 2022-05-20 12:43

MOT test number 668508094080

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Bay covers

**MOT #10** 2022-05-20 12:43**MOT test number** 408776230562**Result** ✗ Failed**Advice** Bay covers**Pass with rectification** Rear Direction indicator incorrect colour both sides (4.4.3 (a))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2021-08-05 08:57**MOT test number** 506855209978**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened Corroded. (1.1.14 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Rear Inner Brake disc worn, pitted or scored, but not seriously weakened Corroded. (1.1.14 (a) (ii))**MOT #8** 2020-08-17 08:51**MOT test number** 171388868121**Result** ✓ Passed**MOT #7** 2019-04-23 09:29**MOT test number** 841600784840**Result** ✓ Passed**MOT #6** 2018-05-10 13:50**MOT test number** 638929803974**Result** ✓ Passed

**MOT #5** 2017-02-20 10:43**MOT test number** 202042473035**Result** ✓ Passed**MOT #4** 2016-03-01 14:40**MOT test number** 521729322520**Result** ✓ Passed**MOT #3** 2015-02-28 11:37**MOT test number** 428539855069**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-02-03 16:31**MOT test number** 826734134068**Result** ✓ Passed**MOT #1** 2014-01-27 12:52**MOT test number** 188407524465**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
19 May 2024

Tax status	Valid until 1 February
Days left	279
MOT expiry date	19 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-01
Last registration	2023-05-10
Complete history	See info



Registration #1	2011-03-01	17 mi
Registration #2	2014-01-27	32.199 mi
Registration #3	2014-02-03	32.721 mi
Registration #4	2015-02-28	45.103 mi
Registration #5	2016-03-01	46.229 mi
Registration #6	2017-02-20	46.468 mi
Registration #7	2018-05-10	47.186 mi
Registration #8	2019-04-23	57.572 mi
Registration #9	2020-05-20	58.277 mi
Registration #10	2021-05-20	58.277 mi
Registration #11	2022-05-20	58.277 mi
Registration #12	2023-05-20	58.277 mi
Registration #13	2024-05-20	58.277 mi
Registration #14	2025-05-20	58.277 mi
Registration #15	2026-05-20	58.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1708102