



PEUGEOT



YY06ERU


report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Blue
Year of manufacture	2006
Top speed	119 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.2 mpg
CO2 emission	178 g/km
CO2 label	I





Internet history

Entry 3

Date 2021-11-01

Pictures 5

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 2

Date 2021-10-27

Pictures 5

Listing price [View report](#)




source: [autotrader.co.uk](https://www.autotrader.co.uk)

Entry 1

Date 2021-10-20

Pictures 5

Listing price [View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-06-30
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	34
Total items failed	12

MOT #20	2023-06-15 10:29
MOT test number	510811929547
Result	✓ Passed
Next expiry date	2024-06-30
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Minor	Nearside Windscreen wiper blade defective split on end (3.4 (b) (i))

**MOT #19**

2022-07-01 11:27

MOT test number

257607544767

Result

✓ Passed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tread area (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Rear exhaust silencer corroded

MOT #18

2021-06-11 15:11

MOT test number

645011487255

Result

✓ Passed

- Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Central Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement both trailing arms (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #17

2020-01-29 11:31

MOT test number

977054839257

Result

✓ Passed

**MOT #16** 2020-01-29 11:31**MOT test number** 594432681132**Result** ✗ Failed**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2018-02-23 14:03**MOT test number** 299086824767**Result** ✓ Passed**MOT #14** 2017-03-03 15:44**MOT test number** 594226911867**Result** ✓ Passed**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2016-03-04 15:46**MOT test number** 785589645067**Result** ✓ Passed**Advice** Slight play o/s inner track rod joint**MOT #12** 2015-03-04 16:57**MOT test number** 467353365019**Result** ✓ Passed

**MOT #11** 2015-03-04 13:59**MOT test number** 838583065008**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Rear Stop lamp not working (1.2.1b)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #10** 2014-03-06 11:39**MOT test number** 265305764088**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #9** 2013-03-08 13:21**MOT test number** 617087063020**Result** ✓ Passed**Notice** Rear brake pads worn low**MOT #8** 2013-03-08 13:21**MOT test number** 998257063092**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Rear brake pads worn low**MOT #7** 2012-04-12 16:39**MOT test number** 296753802497**Result** ✓ Passed

**MOT #6** 2012-04-12 11:24**MOT test number** 197933802172**Result** ✗ Failed

- Notice** Both front tyres wearing on edges
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #5 2011-04-21 09:38**MOT test number** 586541611148**Result** ✓ Passed

- Notice** Nearside rear tyre wearing low
- Notice** Rear brake discs grooved

MOT #4 2010-04-13 12:47**MOT test number** 321073100148**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside rear side light not working

MOT #3 2010-04-13 12:47**MOT test number** 502343500134**Result** ✗ Failed

- Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside rear side light not working



MOT #2	2009-04-16 16:24
MOT test number	404196809175
Result	✓ Passed

MOT #1	2009-04-16 12:49
MOT test number	663636609153
Result	✗ Failed
Fail	Nearside Front Headlamp not working on main beam (1.7.5a)
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YY06ERU
Plate since	2019-06-28
Current registration	YY06ERU
Plate since	2019-06-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-04-27
Last registration	2023-06-15
Complete history	See info



Registration #1	2006-04-27	25 mi
Registration #2	2009-04-16	17.902 mi
Registration #3	2009-04-16	17.902 mi
Registration #4	2010-04-13	26.928 mi
Registration #5	2011-04-21	36.183 mi
Registration #6	2012-04-12	44.237 mi
Registration #7	2012-04-12	44.237 mi
Registration #8	2013-03-08	49.630 mi
Registration #9	2014-03-06	65.229 mi
Registration #10	2015-03-04	82.453 mi
Registration #11	2015-03-04	82.453 mi
Registration #12	2016-03-04	99.677 mi
Registration #13	2017-03-04	116.901 mi
Registration #14	2018-03-04	134.125 mi
Registration #15	2019-03-04	151.349 mi
Registration #16	2020-03-04	168.573 mi
Registration #17	2021-03-04	185.797 mi
Registration #18	2022-03-04	203.021 mi
Registration #19	2023-03-04	220.245 mi
Registration #20	2024-03-04	237.469 mi
Registration #21	2025-03-04	254.693 mi
Registration #22	2026-03-04	271.917 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1528 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	FX6P2862643